

VMware Deliverable Release Notes

This document does not apply to HPE Superdome servers. For information on HPE Superdome, see the following links:

[HPE Integrity Superdome X](#)

[HPE Superdome Flex](#)

Information on HPE Synergy supported VMware ESXi OS releases, HPE ESXi Custom Images and HPE Synergy Custom SPPs is available at:

[OS Support Tool for HPE Synergy](#)

Information on HPE Synergy Software Releases is available at:

[HPE Synergy Software Releases - Overview](#)

Gen10 SPP 2024.09.00.00 Release Notes for VMware ESXi 8.0

[BIOS - System ROM](#)
[Driver - Lights-Out Management](#)
[Driver - Network](#)
[Driver - Storage Controller](#)
[Firmware - Network](#)
[Firmware - Storage Controller](#)
[Firmware - Storage Fibre Channel](#)
[Software - Management](#)
[Software - Storage Controller](#)
[Software - Storage Fibre Channel](#)
[Software - System Management](#)

BIOS - System ROM

[Top](#)

ROM Flash Firmware Package - HPE Apollo 4200 Gen10/HPE ProLiant XL420 Gen10 (U39) Servers

Version: 3.30_07-31-2024 (**Recommended**)

Filename: U39_3.30_07_31_2024.fwpkg

Important Note!

Important Notes:

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2024.3 guidance. This version of the System ROM should be paired with Server Platform Services (SPS) Firmware 04.01.05.002.

Deliverable Name:

HPE Apollo 4200 Gen10/ProLiant XL420 Gen10 System ROM - U39

Release Version:

3.30_07-31-2024

Last Recommended or Critical Revision:

3.30_07-31-2024

Previous Revision:

3.20_05-27-2024

Firmware Dependencies:

None

Enhancements/New Features:

None

Problems Fixed:

Addressed an issue where NS204i may not be identified as an NVMe device.

Addressed an issue where the Logical Drive name was cleared in RBSU after leaving the configuration page of an MR controller.

Addressed an issue where the "Physical Drive missing" message appeared twice in POST when a drive was removed and rebooted with incorrect severity in IML.

Addressed an issue where the boot order was cleared unexpectedly after configuring System Configuration (RBSU) options and navigating to Boot Options > UEFI Boot Settings > UEFI Boot Order, and then pressing F12 to Save and Exit.

Known Issues:

None

Fixes

Important Notes:

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2024.3 guidance. This version of the System ROM should be paired with Server Platform Services (SPS) Firmware 04.01.05.002.

Firmware Dependencies:

None

Problems Fixed:

Addressed an issue where NS204i may not be identified as an NVMe device.

Addressed an issue where the Logical Drive name was cleared in RBSU after leaving the configuration page of an MR controller.

Addressed an issue where the "Physical Drive missing" message appeared twice in POST when a drive was removed and rebooted with incorrect severity in IML.

Addressed an issue where the boot order was cleared unexpectedly after configuring System Configuration (RBSU) options and navigating to Boot Options > UEFI Boot Settings > UEFI Boot Order, and then pressing F12 to Save and Exit.

Known Issues:

None

ROM Flash Firmware Package - HPE Apollo 4510 Gen10/HPE ProLiant XL450 Gen10 (U40) Servers
Version: 3.30_07-31-2024 (**Recommended**)
Filename: U40_3.30_07_31_2024.fwpkg

Important Note!

Important Notes:

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2024.3 guidance. This version of the System ROM should be paired with Server Platform Services (SPS) Firmware 04.01.05.002.

Deliverable Name:

HPE Apollo 4510 Gen10/HPE ProLiant XL450 Gen10 System ROM - U40

Release Version:

3.30_07-31-2024

Last Recommended or Critical Revision:

3.30_07-31-2024

Previous Revision:

3.20_05-27-2024

Firmware Dependencies:

None

Enhancements/New Features:

None

Problems Fixed:

Addressed an issue where NS204i may not be identified as an NVMe device.

Addressed an issue where the Logical Drive name was cleared in RBSU after leaving the configuration page of an MR controller.

Addressed an issue where the "Physical Drive missing" message appeared twice in POST when a drive was removed and rebooted with incorrect severity in IML.

Addressed an issue where the boot order was cleared unexpectedly after configuring System Configuration (RBSU) options and navigating to Boot Options > UEFI Boot Settings > UEFI Boot Order, and then pressing F12 to Save and Exit.

Known Issues:

None

Fixes

Important Notes:

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2024.3 guidance. This

version of the System ROM should be paired with Server Platform Services (SPS) Firmware 04.01.05.002.

Firmware Dependencies:

None

Problems Fixed:

Addressed an issue where NS204i may not be identified as an NVMe device.

Addressed an issue where the Logical Drive name was cleared in RBSU after leaving the configuration page of an MR controller.

Addressed an issue where the "Physical Drive missing" message appeared twice in POST when a drive was removed and rebooted with incorrect severity in IML.

Addressed an issue where the boot order was cleared unexpectedly after configuring System Configuration (RBSU) options and navigating to Boot Options > UEFI Boot Settings > UEFI Boot Order, and then pressing F12 to Save and Exit.

Known Issues:

None

ROM Flash Firmware Package - HPE ProLiant DL160 Gen10/DL180 Gen10 (U31) Servers

Version: 3.30_07-31-2024 (**Recommended**)

Filename: U31_3.30_07_31_2024.fwpkg

Important Note!

Important Notes:

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2024.3 guidance. This version of the System ROM should be paired with Server Platform Services (SPS) Firmware 04.01.05.002.

Deliverable Name:

HPE ProLiant DL160 Gen10/DL180 Gen10 System ROM - U31

Release Version:

3.30_07-31-2024

Last Recommended or Critical Revision:

3.30_07-31-2024

Previous Revision:

3.20_05-27-2024

Firmware Dependencies:

None

Enhancements/New Features:

None

Problems Fixed:

Addressed an issue where NS204i may not be identified as an NVMe device.

Addressed an issue where the Logical Drive name was cleared in RBSU after leaving the configuration page of an MR controller.

Addressed an issue where the "Physical Drive missing" message appeared twice in POST when a drive was removed and rebooted with incorrect severity in IML.

Addressed an issue where the boot order was cleared unexpectedly after configuring System Configuration (RBSU) options and navigating to Boot Options > UEFI Boot Settings > UEFI Boot Order, and then pressing F12 to Save and Exit.

Known Issues:

None

Fixes

Important Notes:

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2024.3 guidance. This version of the System ROM should be paired with Server Platform Services (SPS) Firmware 04.01.05.002.

Firmware Dependencies:

None

Problems Fixed:

Addressed an issue where NS204i may not be identified as an NVMe device.

Addressed an issue where the Logical Drive name was cleared in RBSU after leaving the configuration page of an MR controller.

Addressed an issue where the "Physical Drive missing" message appeared twice in POST when a drive was removed and rebooted with incorrect severity in IML.

Addressed an issue where the boot order was cleared unexpectedly after configuring System Configuration (RBSU) options and navigating to Boot Options > UEFI Boot Settings > UEFI Boot Order, and then pressing F12 to Save and Exit.

Known Issues:

None

ROM Flash Firmware Package - HPE ProLiant DL20 Gen10 (U43) Servers

Version: 3.40_08-01-2024 **(Recommended)**

Filename: U43_3.40_08_01_2024.fwpkg

Important Note!**Important Notes:**

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2024.3 guidance. This version of the System ROM should be paired with Server Platform Services (SPS) Firmware 05.01.04.913.

Deliverable Name:

HPE DL20 Gen10 System ROM - U43

Release Version:

3.40_08-01-2024

Last Recommended or Critical Revision:

3.40_08-01-2024

Previous Revision:

3.10_05-16-2024

Firmware Dependencies:

None

Enhancements/New Features:

None

Problems Fixed:

Addressed an issue where NS204i may not be identified as an NVMe device.

Addressed an issue where the Logical Drive name was cleared in RBSU after leaving the configuration page of an MR controller.

Addressed an issue where WHLK HSTI test failed.

Addressed an issue where the "Physical Drive missing" message appears twice in POST when a drive was removed and rebooted with incorrect severity in IML.

Addressed an issue where the boot order was cleared unexpectedly after configuring System Configuration (RBSU) options and navigating to Boot Options > UEFI Boot Settings > UEFI Boot Order, and then pressing F12 to Save and Exit.

Addressed an issue where system may encounter an RSOD while updating the SAS drive FW via HPE Service Packs, including, but not limited to, VMware ESXi Online HDD FW Component Bundle 16.00, HPE Synergy Service Pack (SSP) 2024.01.02 (January 2024) and the future HPE Synergy Service Pack (SSP) 2024.07.01 (July 2024).

Known Issues:

None

Fixes

Important Notes:

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2024.3 guidance. This version of the System ROM should be paired with Server Platform Services (SPS) Firmware 05.01.04.913.

Firmware Dependencies:

None

Problems Fixed:

Addressed an issue where NS204i may not be identified as an NVMe device.

Addressed an issue where the Logical Drive name was cleared in RBSU after leaving the configuration page of an MR controller.

Addressed an issue where WHLK HSTI test failed.

Addressed an issue where the "Physical Drive missing" message appears twice in POST when a drive was removed and rebooted with incorrect severity in IML.

Addressed an issue where the boot order was cleared unexpectedly after configuring System Configuration (RBSU) options and navigating to Boot Options > UEFI Boot Settings > UEFI Boot Order, and then pressing F12 to Save and Exit.

Addressed an issue where system may encounter an RSOD while updating the SAS drive FW via HPE Service Packs, including, but not limited to, VMware ESXi Online HDD FW Component Bundle 16.00, HPE Synergy Service Pack (SSP) 2024.01.02 (January 2024) and the future HPE Synergy Service Pack (SSP) 2024.07.01 (July 2024).

Known Issues:

None

ROM Flash Firmware Package - HPE Proliant DL20 Gen10 Plus Servers
Version: 2.20_08-07-2024 (**Recommended**)
Filename: U60_2.20_08_07_2024.fwpkg

Important Note!**Important Notes:**

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2024.3 guidance.

This version of the System ROM should be paired with Server Platform Services (SPS) Firmware 06.00.03.604 (2.00_12_20_2023).

Deliverable Name:

HPE DL20 Gen10 Plus System ROM - U60

Release Version:

2.20_08-07-2024

Last Recommended or Critical Revision:

2.20_08-07-2024

Previous Revision:

2.10_05-16-2024

Firmware Dependencies:

None

Enhancements/New Features:

None

Problems Fixed:

Addressed an issue where NS204i may not be identified as an NVMe device.

Addressed an issue where the Logical Drive name was cleared in RBSU after leaving configuration page of an MR controller.

Addressed an issue that Battery Failure IML message log may be incorrectly logged for MR Controller with Smart Storage Battery.

Addressed an issue where system failed to boot with selected NVMe HDD by setting One-Time Boot Option in ILO Web.

Addressed an issue where system may encounter a RSOD while updating SAS drive FW via HPE Service Packs, including, but not limited to, VMware ESXi Online HDD FW Component Bundle 16.00, HPE Synergy Service Pack (SSP) 2024.01.02 (January 2024) and the future HPE Synergy Service Pack (SSP) 2024.07.01 (July 2024).

Known Issues:

None

Fixes**Important Notes:**

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2024.3 guidance.

This version of the System ROM should be paired with Server Platform Services (SPS) Firmware 06.00.03.604 (2.00_12_20_2023).

Firmware Dependencies:

None

Problems Fixed:

Addressed an issue where NS204i may not be identified as an NVMe device.

Addressed an issue where the Logical Drive name was cleared in RBSU after leaving configuration page of an MR controller.

Addressed an issue that Battery Failure IML message log may be incorrectly logged for MR Controller with Smart Storage Battery.

Addressed an issue where system failed to boot with selected NVMe HDD by setting One-Time Boot Option in ILO Web.

Addressed an issue where system may encounter a RSOD while updating SAS drive FW via HPE Service Packs, including, but not limited to, VMware ESXi Online HDD FW Component Bundle 16.00, HPE Synergy Service Pack (SSP) 2024.01.02 (January 2024) and the future HPE Synergy Service Pack (SSP) 2024.07.01 (July 2024).

Known Issues:

None

Enhancements

Updated some Japanese translation.

ROM Flash Firmware Package - HPE ProLiant DL325 Gen10 (A41) Servers

Version: 3.20_07-04-2024 (**Optional**)

Filename: A41_3.20_07_04_2024.fwpkg

Important Note!**Important Notes:**

This revision of the System ROM includes AMD reference code RomePI 1.0.0.J for AMD 2nd Generation EPYC processors. This revision of the System ROM includes AMD reference code NaplesPI 1.0.0.M for AMD 1st Generation EPYC processors.

Deliverable Name:

HPE ProLiant DL325 Gen10 System ROM - A41

Release Version:

3.20_07-04-2024

Last Recommended or Critical Revision:

3.10_05-16-2024

Previous Revision:

3.10_05-16-2024

Firmware Dependencies:

None

Enhancements/New Features:

None

Problems Fixed:

Addressed an issue where the boot order was cleared unexpectedly after configuring System Configuration (RBSU) options, navigating to Boot Options > UEFI Boot Settings > UEFI Boot Order, and then pressing F12 to Save and Exit.

Addressed an issue where system may encounter a RSOD while updating SAS drive FW via HPE Service Packs, including, but not

limited to, VMware ESXi Online HDD FW Component Bundle 16.00, HPE Synergy Service Pack (SSP) 2024.01.02 (January 2024) and the future HPE Synergy Service Pack (SSP) 2024.07.01 (July 2024).

Addressed an issue where the Logical Drive name was cleared in RBSU after leaving configuration page of MR controller.

Addressed an issue where duplicated "Physical Drive missing" may appear in POST and IML.

Known Issues:

None

Fixes

Important Notes:

This revision of the System ROM includes AMD reference code RomePI 1.0.0.J for AMD 2nd Generation EPYC processors. This revision of the System ROM includes AMD reference code NaplesPI 1.0.0.M for AMD 1st Generation EPYC processors.

Firmware Dependencies:

None

Problems Fixed:

Addressed an issue where the boot order was cleared unexpectedly after configuring System Configuration (RBSU) options, navigating to Boot Options > UEFI Boot Settings > UEFI Boot Order, and then pressing F12 to Save and Exit.

Addressed an issue where system may encounter a RSOD while updating SAS drive FW via HPE Service Packs, including, but not limited to, VMware ESXi Online HDD FW Component Bundle 16.00, HPE Synergy Service Pack (SSP) 2024.01.02 (January 2024) and the future HPE Synergy Service Pack (SSP) 2024.07.01 (July 2024).

Addressed an issue where the Logical Drive name was cleared in RBSU after leaving configuration page of MR controller.

Addressed an issue where duplicated "Physical Drive missing" may appear in POST and IML.

Known Issues:

None

ROM Flash Firmware Package - HPE ProLiant DL360 Gen10 (U32) Servers

Version: 3.30_07-31-2024 (**Recommended**)

Filename: U32_3.30_07_31_2024.fwpkg

Important Note!

Important Notes:

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2024.3 guidance. This version of the System ROM should be paired with Server Platform Services (SPS) Firmware 04.01.05.002.

Deliverable Name:

HPE ProLiant DL360 Gen10 System ROM - U32

Release Version:

3.30_07-31-2024

Last Recommended or Critical Revision:

3.30_07-31-2024

Previous Revision:

3.20_05-27-2024

Firmware Dependencies:

None

Enhancements/New Features:

None

Problems Fixed:

Addressed an issue where NS204i may not be identified as an NVMe device.

Addressed an issue where the Logical Drive name was cleared in RBSU after leaving the configuration page of an MR controller.

Addressed an issue where the "Physical Drive missing" message appeared twice in POST when a drive was removed and rebooted with incorrect severity in IML.

Addressed an issue where the boot order was cleared unexpectedly after configuring System Configuration (RBSU) options and navigating to Boot Options > UEFI Boot Settings > UEFI Boot Order, and then pressing F12 to Save and Exit.

Known Issues:

None

Fixes

Important Notes:

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2024.3 guidance. This version of the System ROM should be paired with Server Platform Services (SPS) Firmware 04.01.05.002.

Firmware Dependencies:

None

Problems Fixed:

Addressed an issue where NS204i may not be identified as an NVMe device.

Addressed an issue where the Logical Drive name was cleared in RBSU after leaving the configuration page of an MR controller.

Addressed an issue where the "Physical Drive missing" message appeared twice in POST when a drive was removed and rebooted with incorrect severity in IML.

Addressed an issue where the boot order was cleared unexpectedly after configuring System Configuration (RBSU) options and navigating to Boot Options > UEFI Boot Settings > UEFI Boot Order, and then pressing F12 to Save and Exit.

Known Issues:

None

ROM Flash Firmware Package - HPE ProLiant DL380 Gen10 (U30) Servers
Version: 3.30_07-31-2024 **(Recommended)**
Filename: U30_3.30_07_31_2024.fwpkg

Important Note!

Important Notes:

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2024.3 guidance. This version of the System ROM should be paired with Server Platform Services (SPS) Firmware 04.01.05.002.

Deliverable Name:

HPE ProLiant DL380 Gen10 System ROM - U30

Release Version:

3.30_07-31-2024

Last Recommended or Critical Revision:

3.30_07-31-2024

Previous Revision:

3.20_05-27-2024

Firmware Dependencies:

None

Enhancements/New Features:

None

Problems Fixed:

Addressed an issue where NS204i may not be identified as an NVMe device.

Addressed an issue where the Logical Drive name was cleared in RBSU after leaving the configuration page of an MR controller.

Addressed an issue where the "Physical Drive missing" message appeared twice in POST when a drive was removed and rebooted

with incorrect severity in IML.

Addressed an issue where the boot order was cleared unexpectedly after configuring System Configuration (RBSU) options and navigating to Boot Options > UEFI Boot Settings > UEFI Boot Order, and then pressing F12 to Save and Exit.

Known Issues:

None

Fixes

Important Notes:

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2024.3 guidance. This version of the System ROM should be paired with Server Platform Services (SPS) Firmware 04.01.05.002.

Firmware Dependencies:

None

Problems Fixed:

Addressed an issue where NS204i may not be identified as an NVMe device.

Addressed an issue where the Logical Drive name was cleared in RBSU after leaving the configuration page of an MR controller.

Addressed an issue where the "Physical Drive missing" message appeared twice in POST when a drive was removed and rebooted with incorrect severity in IML.

Addressed an issue where the boot order was cleared unexpectedly after configuring System Configuration (RBSU) options and navigating to Boot Options > UEFI Boot Settings > UEFI Boot Order, and then pressing F12 to Save and Exit.

Known Issues:

None

ROM Flash Firmware Package - HPE ProLiant DL385 Gen10 (A40) Servers

Version: 3.20_07-04-2024 (**Optional**)

Filename: A40_3.20_07_04_2024.fwpkg

Important Note!

Important Notes:

This revision of the System ROM includes AMD reference code RomePI 1.0.0.J for AMD 2nd Generation EPYC processors. This revision of the System ROM includes AMD reference code NaplesPI 1.0.0.M for AMD 1st Generation EPYC processors.

Deliverable Name:

HPE DL385 Gen10 System ROM - A40

Release Version:

3.20_07-04-2024

Last Recommended or Critical Revision:

3.10_05-16-2024

Previous Revision:

3.10_05-16-2024

Firmware Dependencies:

None

Enhancements/New Features:

None

Problems Fixed:

Addressed an issue where the boot order was cleared unexpectedly after configuring System Configuration (RBSU) options, navigating to Boot Options > UEFI Boot Settings > UEFI Boot Order, and then pressing F12 to Save and Exit.

Addressed an issue where system may encounter a RSOD while updating SAS drive FW via HPE Service Packs, including, but not limited to, VMware ESXi Online HDD FW Component Bundle 16.00, HPE Synergy Service Pack (SSP) 2024.01.02 (January 2024) and the future HPE Synergy Service Pack (SSP) 2024.07.01 (July 2024).

Addressed an issue where the Logical Drive name was cleared in RBSU after leaving configuration page of MR controller.

Addressed an issue where duplicated "Physical Drive missing" may appear in POST and IML.

Known Issues:

None

Fixes

Important Notes:

This revision of the System ROM includes AMD reference code RomePI 1.0.0.J for AMD 2nd Generation EPYC processors. This revision of the System ROM includes AMD reference code NaplesPI 1.0.0.M for AMD 1st Generation EPYC processors.

Firmware Dependencies:

None

Problems Fixed:

Addressed an issue where the boot order was cleared unexpectedly after configuring System Configuration (RBSU) options, navigating to Boot Options > UEFI Boot Settings > UEFI Boot Order, and then pressing F12 to Save and Exit.

Addressed an issue where system may encounter a RSOD while updating SAS drive FW via HPE Service Packs, including, but not limited to, VMware ESXi Online HDD FW Component Bundle 16.00, HPE Synergy Service Pack (SSP) 2024.01.02 (January 2024) and the future HPE Synergy Service Pack (SSP) 2024.07.01 (July 2024).

Addressed an issue where the Logical Drive name was cleared in RBSU after leaving configuration page of MR controller.

Addressed an issue where duplicated "Physical Drive missing" may appear in POST and IML.

Known Issues:

None

ROM Flash Firmware Package - HPE ProLiant DL560 Gen10/DL580 Gen10 (U34) Servers

Version: 3.30_07-31-2024 (**Recommended**)

Filename: U34_3.30_07_31_2024.fwpkg

Important Note!

Important Notes:

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2024.3 guidance. This version of the System ROM should be paired with Server Platform Services (SPS) Firmware 04.01.05.002.

Deliverable Name:

HPE ProLiant DL560 Gen10/DL580 Gen10 System ROM - U34

Release Version:

3.30_07-31-2024

Last Recommended or Critical Revision:

3.30_07-31-2024

Previous Revision:

3.20_05-27-2024

Firmware Dependencies:

None

Enhancements/New Features:

None

Problems Fixed:

Addressed an issue where NS204i may not be identified as an NVMe device.

Addressed an issue where the Logical Drive name was cleared in RBSU after leaving the configuration page of an MR controller.

Addressed an issue where the "Physical Drive missing" message appeared twice in POST when a drive was removed and rebooted with incorrect severity in IML.

Addressed an issue where the boot order was cleared unexpectedly after configuring System Configuration (RBSU) options and navigating to Boot Options > UEFI Boot Settings > UEFI Boot Order, and then pressing F12 to Save and Exit.

Known Issues:

None

Fixes

Important Notes:

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2024.3 guidance. This version of the System ROM should be paired with Server Platform Services (SPS) Firmware 04.01.05.002.

Firmware Dependencies:

None

Problems Fixed:

Addressed an issue where NS204i may not be identified as an NVMe device.

Addressed an issue where the Logical Drive name was cleared in RBSU after leaving the configuration page of an MR controller.

Addressed an issue where the "Physical Drive missing" message appeared twice in POST when a drive was removed and rebooted with incorrect severity in IML.

Addressed an issue where the boot order was cleared unexpectedly after configuring System Configuration (RBSU) options and navigating to Boot Options > UEFI Boot Settings > UEFI Boot Order, and then pressing F12 to Save and Exit.

Known Issues:

None

ROM Flash Firmware Package - HPE ProLiant MicroServer Gen10 Plus v2 (U64) Servers
Version: 2.20_08-07-2024 **(Recommended)**
Filename: U64_2.20_08_07_2024.fwpkg

Important Note!

Important Notes:

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2024.3 guidance.

This version of the System ROM should be paired with Server Platform Services (SPS) Firmware 06.00.03.604 (2.00_12_20_2023).

Deliverable Name:

HPE ProLiant MicroServer Gen10 Plus v2 System ROM - U64

Release Version:

2.20_08-07-2024

Last Recommended or Critical Revision:

2.20_08-07-2024

Previous Revision:

2.10_05-16-2024

Firmware Dependencies:

None

Enhancements/New Features:

None

Problems Fixed:

Addressed an issue where NS204i may not be identified as an NVMe device.

Addressed an issue where the Logical Drive name was cleared in RBSU after leaving configuration page of an MR controller.

Addressed an issue that Battery Failure IML message log may be incorrectly logged for MR Controller with Smart Storage Battery.

Addressed an issue where system failed to boot with selected NVMe HDD by setting One-Time Boot Option in ILO Web.

Addressed an issue where system may encounter a RSOD while updating SAS drive FW via HPE Service Packs, including, but not limited to, VMware ESXi Online HDD FW Component Bundle 16.00, HPE Synergy Service Pack (SSP) 2024.01.02 (January 2024) and the future HPE Synergy Service Pack (SSP) 2024.07.01 (July 2024).

Known Issues:

None

Fixes

Important Notes:

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2024.3 guidance.

This version of the System ROM should be paired with Server Platform Services (SPS) Firmware 06.00.03.604 (2.00_12_20_2023).

Firmware Dependencies:

None

Problems Fixed:

Addressed an issue where NS204i may not be identified as an NVMe device.

Addressed an issue where the Logical Drive name was cleared in RBSU after leaving configuration page of an MR controller.

Addressed an issue that Battery Failure IML message log may be incorrectly logged for MR Controller with Smart Storage Battery.

Addressed an issue where system failed to boot with selected NVMe HDD by setting One-Time Boot Option in ILO Web.

Addressed an issue where system may encounter a RSOD while updating SAS drive FW via HPE Service Packs, including, but not limited to, VMware ESXi Online HDD FW Component Bundle 16.00, HPE Synergy Service Pack (SSP) 2024.01.02 (January 2024) and the future HPE Synergy Service Pack (SSP) 2024.07.01 (July 2024).

Known Issues:

None

Enhancements

Updated some Japanese translation.

ROM Flash Firmware Package - HPE ProLiant ML110 Gen10 (U33) Servers

Version: 3.30_07-31-2024 (**Recommended**)

Filename: U33_3.30_07_31_2024.fwpkg

Fixes

See the release document U33_3.30_07_31_2024 in Download Product Binaries page from Product Summary of the firmware product.

Enhancements

See the release document U33_3.30_07_31_2024 in Download Product Binaries page from Product Summary of the firmware product.

ROM Flash Firmware Package - HPE ProLiant ML30 Gen10 (U44) Servers

Version: 3.40_08-01-2024 (**Recommended**)

Filename: U44_3.40_08_01_2024.fwpkg

Important Note!

Important Notes:

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2024.3 guidance. This version of the System ROM should be paired with Server Platform Services (SPS) Firmware 05.01.04.913.

Deliverable Name:

HPE ProLiant ML30 Gen10 System ROM - U44

Release Version:

3.40_08-01-2024

Last Recommended or Critical Revision:

3.40_08-01-2024

Previous Revision:

3.10_05-16-2024

Firmware Dependencies:

None

Enhancements/New Features:

None

Problems Fixed:

Addressed an issue where NS204i may not be identified as an NVMe device.

Addressed an issue where the Logical Drive name was cleared in RBSU after leaving the configuration page of an MR controller.

Addressed an issue where WHLK HSTI test failed.

Addressed an issue where the "Physical Drive missing" message appears twice in POST when a drive was removed and rebooted with incorrect severity in IML.

Addressed an issue where the boot order was cleared unexpectedly after configuring System Configuration (RBSU) options and navigating to Boot Options > UEFI Boot Settings > UEFI Boot Order, and then pressing F12 to Save and Exit.

Addressed an issue where system may encounter an RSOD while updating the SAS drive FW via HPE Service Packs, including, but not limited to, VMware ESXi Online HDD FW Component Bundle 16.00, HPE Synergy Service Pack (SSP) 2024.01.02 (January 2024) and the future HPE Synergy Service Pack (SSP) 2024.07.01 (July 2024).

Known Issues:

None

Fixes**Important Notes:**

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2024.3 guidance. This version of the System ROM should be paired with Server Platform Services (SPS) Firmware 05.01.04.913.

Firmware Dependencies:

None

Problems Fixed:

Addressed an issue where NS204i may not be identified as an NVMe device.

Addressed an issue where the Logical Drive name was cleared in RBSU after leaving the configuration page of an MR controller.

Addressed an issue where WHLK HSTI test failed.

Addressed an issue where the "Physical Drive missing" message appears twice in POST when a drive was removed and rebooted with incorrect severity in IML.

Addressed an issue where the boot order was cleared unexpectedly after configuring System Configuration (RBSU) options and navigating to Boot Options > UEFI Boot Settings > UEFI Boot Order, and then pressing F12 to Save and Exit.

Addressed an issue where system may encounter an RSOD while updating the SAS drive FW via HPE Service Packs, including, but not limited to, VMware ESXi Online HDD FW Component Bundle 16.00, HPE Synergy Service Pack (SSP) 2024.01.02 (January 2024) and the future HPE Synergy Service Pack (SSP) 2024.07.01 (July 2024).

Known Issues:

None

ROM Flash Firmware Package - HPE ProLiant ML30 Gen10 Plus Servers

Version: 2.20_08-07-2024 **(Recommended)**

Filename: U61_2.20_08_07_2024.fwpkg

Important Note!**Important Notes:**

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2024.3 guidance.
This version of the System ROM should be paired with Server Platform Services (SPS) Firmware 06.00.03.604 (2.00_12_20_2023).

Deliverable Name:

HPE ProLiant ML30 Gen10 Plus System ROM - U61

Release Version:

2.20_08-07-2024

Last Recommended or Critical Revision:

2.20_08-07-2024

Previous Revision:

2.10_05-16-2024

Firmware Dependencies:

None

Enhancements/New Features:

None

Problems Fixed:

Addressed an issue where NS204i may not be identified as an NVMe device.

Addressed an issue where the Logical Drive name was cleared in RBSU after leaving configuration page of an MR controller.

Addressed an issue that Battery Failure IML message log may be incorrectly logged for MR Controller with Smart Storage Battery.

Addressed an issue where system failed to boot with selected NVMe HDD by setting One-Time Boot Option in ILO Web.

Addressed an issue where system may encounter a RSOD while updating SAS drive FW via HPE Service Packs, including, but not limited to, VMware ESXi Online HDD FW Component Bundle 16.00, HPE Synergy Service Pack (SSP) 2024.01.02 (January 2024) and the future HPE Synergy Service Pack (SSP) 2024.07.01 (July 2024).

Known Issues:

None

Fixes

Important Notes:

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2024.3 guidance.
This version of the System ROM should be paired with Server Platform Services (SPS) Firmware 06.00.03.604 (2.00_12_20_2023).

Firmware Dependencies:

None

Problems Fixed:

Addressed an issue where NS204i may not be identified as an NVMe device.

Addressed an issue where the Logical Drive name was cleared in RBSU after leaving configuration page of an MR controller.

Addressed an issue that Battery Failure IML message log may be incorrectly logged for MR Controller with Smart Storage Battery.

Addressed an issue where system failed to boot with selected NVMe HDD by setting One-Time Boot Option in ILO Web.

Addressed an issue where system may encounter a RSOD while updating SAS drive FW via HPE Service Packs, including, but not limited to, VMware ESXi Online HDD FW Component Bundle 16.00, HPE Synergy Service Pack (SSP) 2024.01.02 (January 2024) and the future HPE Synergy Service Pack (SSP) 2024.07.01 (July 2024).

Known Issues:

None

Enhancements

Updated some Japanese translation.

Important Note!

Important Notes:

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2024.3 guidance. This version of the System ROM should be paired with Server Platform Services (SPS) Firmware 04.01.05.002.

Deliverable Name:

HPE ProLiant ML350 Gen10 System ROM - U41

Release Version:

3.30_07-31-2024

Last Recommended or Critical Revision:

3.30_07-31-2024

Previous Revision:

3.20_05-27-2024

Firmware Dependencies:

None

Enhancements/New Features:

None

Problems Fixed:

Addressed an issue where NS204i may not be identified as an NVMe device.

Addressed an issue where the Logical Drive name was cleared in RBSU after leaving the configuration page of an MR controller.

Addressed an issue where the "Physical Drive missing" message appeared twice in POST when a drive was removed and rebooted with incorrect severity in IML.

Addressed an issue where the boot order was cleared unexpectedly after configuring System Configuration (RBSU) options and navigating to Boot Options > UEFI Boot Settings > UEFI Boot Order, and then pressing F12 to Save and Exit.

Known Issues:

None

Fixes

Important Notes:

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2024.3 guidance. This version of the System ROM should be paired with Server Platform Services (SPS) Firmware 04.01.05.002.

Firmware Dependencies:

None

Problems Fixed:

Addressed an issue where NS204i may not be identified as an NVMe device.

Addressed an issue where the Logical Drive name was cleared in RBSU after leaving the configuration page of an MR controller.

Addressed an issue where the "Physical Drive missing" message appeared twice in POST when a drive was removed and rebooted with incorrect severity in IML.

Addressed an issue where the boot order was cleared unexpectedly after configuring System Configuration (RBSU) options and navigating to Boot Options > UEFI Boot Settings > UEFI Boot Order, and then pressing F12 to Save and Exit.

Known Issues:

None

Important Note!

Important Notes:

This revision of the System ROM includes AMD reference code MilanPI 1.0.0.D for AMD 3rd Generation EPYC processors.

This revision of the System ROM includes AMD reference code RomePI 1.0.0.J for AMD 2nd Generation EPYC processors.

Deliverable Name:

HPE ProLiant DL325/DL325 v2/DL345 Gen10 Plus System ROM - A43

Release Version:

3.20_08-07-2024

Last Recommended or Critical Revision:

3.20_08-07-2024

Previous Revision:

3.10_05-16-2024

Firmware Dependencies:

None

Enhancements/New Features:

Added the System Configuration (RBSU) option "Processor Options/AMD IC Config Disable IT Bypass" and set to "Disabled" by default. Enable this option if a UMCE with Bank 0x03 and Synd[0]=1 is logged in IML on EPYC 7003 processors.

This setting has the following Redfish property:

/redfish/v1/systems/1/bios/settings/AmdIcConfigDisableITBypass

Problems Fixed:

Addressed an issue where NS204i may not be identified as an NVMe device.

Addressed an issue where the Logical Drive name was cleared in RBSU after leaving the configuration page of the MR controller.

Addressed an issue where Redfish BIOS actions, ResetBIOS and ChangePassword may not work.

Addressed an issue where Battery Failure IML message log may be incorrectly logged for the Smart Array controller with Smart Storage Battery.

Addressed an issue where system failed to boot with selected NVMe HDD by setting One-Time Boot Option in ILO Web.

Addressed an issue where system may encounter a RSOD while updating SAS drive FW via HPE Service Packs, including, but not limited to, VMware ESXi Online HDD FW Component Bundle 16.00, HPE Synergy Service Pack (SSP) 2024.01.02 (January 2024) and the future HPE Synergy Service Pack (SSP) 2024.07.01 (July 2024).

Known Issues:

None

Fixes

Important Notes:

This revision of the System ROM includes AMD reference code MilanPI 1.0.0.D for AMD 3rd Generation EPYC processors.

This revision of the System ROM includes AMD reference code RomePI 1.0.0.J for AMD 2nd Generation EPYC processors.

Firmware Dependencies:

None

Problems Fixed:

Addressed an issue where NS204i may not be identified as an NVMe device.

Addressed an issue where the Logical Drive name was cleared in RBSU after leaving the configuration page of the MR controller.

Addressed an issue where Redfish BIOS actions, ResetBIOS and ChangePassword may not work.

Addressed an issue where Battery Failure IML message log may be incorrectly logged for the Smart Array controller with Smart Storage Battery.

Addressed an issue where system failed to boot with selected NVMe HDD by setting One-Time Boot Option in ILO Web.

Addressed an issue where system may encounter a RSOD while updating SAS drive FW via HPE Service Packs, including, but not limited to, VMware ESXi Online HDD FW Component Bundle 16.00, HPE Synergy Service Pack (SSP) 2024.01.02 (January 2024) and the future HPE Synergy Service Pack (SSP) 2024.07.01 (July 2024).

Known Issues:

None

Enhancements

Added the System Configuration (RBSU) option "Processor Options/AMD IC Config Disable IT Bypass" and set to "Disabled" by default. Enable this option if a UMCE with Bank 0x03 and Synd[0]=1 is logged in IML on EPYC 7003 processors.

This setting has the following Redfish property:

/redfish/v1/systems/1/bios/settings/AmdIcConfigDisableITBypass

ROM Flash Universal Firmware Package - HPE ProLiant DL360/DL380 Gen10 Plus (U46) Servers

Version: 2.20_08-07-2024 (**Recommended**)

Filename: U46_2.20_08_07_2024.fwpkg

Important Note!**Important Notes:**

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2024.3 guidance.

This version of the System ROM should be paired with Server Platform Services (SPS) Firmware 04.04.04.603 (2.00_12_18_2023).

Deliverable Name:

HPE DL360 Gen10 Plus/DL380 Gen10 Plus System ROM - U46

Release Version:

2.20_08-07-2024

Last Recommended or Critical Revision:

2.20_08-07-2024

Previous Revision:

2.12_06_14_2024

Firmware Dependencies:

None

Enhancements/New Features:

Updated some Japanese translation

Problems Fixed:

Addressed an issue where NS204i may not be identified as an NVMe device.

Addressed an issue where the Logical Drive name was cleared in RBSU after leaving the configuration page of the MR controller.

Addressed an issue where Redfish BIOS actions, ResetBIOS and ChangePassword may not work.

Addressed an issue where Battery Failure IML message log may be incorrectly logged for the Smart Array controller with Smart Storage Battery.

Addressed an issue where the driver Health Message was shown twice in POST when drive was removed and ran cold boot.

Known Issues:

None

Fixes**Important Notes:**

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2024.3 guidance.

This version of the System ROM should be paired with Server Platform Services (SPS) Firmware 04.04.04.603 (2.00_12_18_2023).

Firmware Dependencies:

None

Problems Fixed:

Addressed an issue where NS204i may not be identified as an NVMe device.

Addressed an issue where the Logical Drive name was cleared in RBSU after leaving the configuration page of the MR controller.

Addressed an issue where Redfish BIOS actions, ResetBIOS and ChangePassword may not work.

Addressed an issue where Battery Failure IML message log may be incorrectly logged for the Smart Array controller with Smart Storage Battery.

Addressed an issue where the driver Health Message was shown twice in POST when drive was removed and ran cold boot.

Known Issues:

None

Enhancements

Updated some Japanese translation.

ROM Flash Universal Firmware Package - HPE ProLiant DL365/DL385/DL385 v2 Gen10 Plus (A42) Servers
Version: 3.20_08-07-2024 (**Recommended**)
Filename: A42_3.20_08_07_2024.fwpkg

Important Note!

Important Notes:

This revision of the System ROM includes AMD reference code MilanPI 1.0.0.D for AMD 3rd Generation EPYC processors.

This revision of the System ROM includes AMD reference code RomePI 1.0.0.J for AMD 2nd Generation EPYC processors.

Deliverable Name:

HPE DL365 Gen10 Plus/DL385 Gen10 Plus/DL385 v2 Gen10 Plus System ROM - A42

Release Version:

3.20_08-07-2024

Last Recommended or Critical Revision:

3.20_08-07-2024

Previous Revision:

3.10_05-16-2024

Firmware Dependencies:

None

Enhancements/New Features:

Added the System Configuration (RBSU) option "Processor Options/AMD IC Config Disable IT Bypass" and set to "Disabled" by default. Enable this option if a UMCE with Bank 0x03 and Synd[0]=1 is logged in IML on EPYC 7003 processors.

This setting has the following Redfish property:

/redfish/v1/systems/1/bios/settings/AmdIcConfigDisableITBypass

Problems Fixed:

Addressed an issue where NS204i may not be identified as an NVMe device.

Addressed an issue where the Logical Drive name was cleared in RBSU after leaving the configuration page of the MR controller.

Addressed an issue where Redfish BIOS actions, ResetBIOS and ChangePassword may not work.

Addressed an issue where Battery Failure IML message log may be incorrectly logged for the Smart Array controller with Smart Storage Battery.

Addressed an issue where system failed to boot with selected NVMe HDD by setting One-Time Boot Option in ILO Web.

Addressed an issue where system may encounter a RSOD while updating SAS drive FW via HPE Service Packs, including, but not limited to, VMware ESXi Online HDD FW Component Bundle 16.00, HPE Synergy Service Pack (SSP) 2024.01.02 (January 2024) and the future HPE Synergy Service Pack (SSP) 2024.07.01 (July 2024).

Known Issues:

None

Fixes

Important Notes:

This revision of the System ROM includes AMD reference code MilanPI 1.0.0.D for AMD 3rd Generation EPYC processors.

This revision of the System ROM includes AMD reference code RomePI 1.0.0.J for AMD 2nd Generation EPYC processors.

Firmware Dependencies:

None

Problems Fixed:

Addressed an issue where NS204i may not be identified as an NVMe device.

Addressed an issue where the Logical Drive name was cleared in RBSU after leaving the configuration page of the MR controller.

Addressed an issue where Redfish BIOS actions, ResetBIOS and ChangePassword may not work.

Addressed an issue where Battery Failure IML message log may be incorrectly logged for the Smart Array controller with Smart Storage Battery.

Addressed an issue where system failed to boot with selected NVMe HDD by setting One-Time Boot Option in ILO Web.

Addressed an issue where system may encounter a RSOD while updating SAS drive FW via HPE Service Packs, including, but not limited to, VMware ESXi Online HDD FW Component Bundle 16.00, HPE Synergy Service Pack (SSP) 2024.01.02 (January 2024) and the future HPE Synergy Service Pack (SSP) 2024.07.01 (July 2024).

Known Issues:

None

Enhancements

Added the System Configuration (RBSU) option "Processor Options/AMD IC Config Disable IT Bypass" and set to "Disabled" by default. Enable this option if a UMCE with Bank 0x03 and Synd[0]=1 is logged in IML on EPYC 7003 processors.

This setting has the following Redfish property:

`/redfish/v1/systems/1/bios/settings/AmdIcConfigDisableITBypass`

Driver - Lights-Out Management

[Top](#)

HPE iLO Native Driver for ESXi 7.0

Version: 10.8.2 (**Recommended**)

Filename: ilo-driver_700.10.8.2.2-1OEM.700.1.0.15843807_22942561.zip

Fixes

This product addressed a memory leak in vmkernel.

Driver - Network

[Top](#)

HPE Broadcom NetXtreme-E Drivers for VMware vSphere 8.0

Version: 2024.09.00 (**Recommended**)

Filename: cp062101.compsig; cp062101.zip

Important Note!

- This component is intended to be used by HPE applications. It is a zip file that contains the same driver deliverable available from the vmware.com and the HPE vibsdepot.hpe.com webpages, plus an HPE specific CP0xxxxx.xml file.
- HPE recommends the *HPE Broadcom NetXtreme-E Firmware Version, 230.1.123000* or later, for use with this driver.

Fixes

This product addresses the problem to enabling NPAR+ SRIOV (more than supported VFs through Driver) causes system failure.

Enhancements

- This product enhances RoCE command size trimming.
- This product enhances driver logging to capture non-supported dual-rate transceiver async errors.

Supported Devices and Features

This product supports the following network adapters:

- HPE Ethernet 10Gb 2-port 535FLR-T Adapter
- HPE Ethernet 10Gb 2-port 535T Adapter
- HPE Ethernet 10Gb 2-port 537SFP+ Adapter
- HPE Ethernet 10Gb 2-port 537SFP+ FLR Adapter

- HPE Ethernet 10/25Gb 2-port 631FLR-SFP28 Adapter
- HPE Ethernet 10/25Gb 2-port 631SFP28 Adapter
- HPE Ethernet 10Gb 2-port SFP+ BCM57412 OCP3 Adapter
- HPE Ethernet 10Gb 2-port SFP+ BCM57412 Adapter
- HPE Ethernet 10Gb 2-port BaseT BCM57416 OCP3 Adapter
- HPE Ethernet 10Gb 2-port BaseT BCM57416 Adapter
- HPE Ethernet 10/25Gb 2-port SFP28 BCM57414 OCP3 Adapter
- HPE Ethernet 10/25Gb 2-port SFP28 BCM57414 Adapter
- Broadcom BCM57504 Ethernet 10/25Gb 4-port SFP28 Adapter for HPE
- Broadcom BCM57504 Ethernet 10/25Gb 4-port SFP28 OCP3 Adapter for HPE

HPE Intel i40en Driver for VMware vSphere 8.0

Version: 2024.09.00 (**Recommended**)

Filename: cp061664.compsig; cp061664.zip

Important Note!

This component is intended to be used by HPE applications. It is a zip file that contains the same driver deliverable available from the vmware.com and the HPE vibsdepot.hpe.com webpages, plus an HPE specific CP0xxxxx.xml file.

HPE recommends the firmware provided in *HPE Intel Online Firmware Upgrade Utility for VMware*, version 3.24.0 or later, for use with this driver.

Enhancements

- This product enhanced to support log FW Failure Critical Data in Recovery Mode.
- This product enhanced to support add module parameters pause_rx and pause_tx for Link Flow Control and enable it by default.

Supported Devices and Features

This product supports the following network adapters:

- HPE Ethernet 1Gb 2-port 368FLR-MMT Adapter
- HPE Ethernet 1Gb 2-port 368i Adapter
- HPE Ethernet 1Gb 4-port 369i Adapter
- HPE Ethernet 10Gb 2-port 562FLR-SFP+ Adapter
- HPE Ethernet 10Gb 2-port 562SFP+ Adapter
- HPE Ethernet 10Gb 2-port 563i Adapter
- HPE Ethernet 10Gb 2-port 568FLR-MMSFP+ Adapter
- HPE Ethernet 10Gb 2-port 568FLR-MMT Adapter
- HPE Ethernet 10Gb 2-port 568i Adapter
- HPE Ethernet 10Gb 2-port SFP+ OCP3 X710-DA2 Adapter
- HPE Ethernet 10Gb 2-port SFP+ X710-DA2 Adapter

HPE Intel igbn Driver for VMware vSphere 8.0

Version: 2024.09.00 (**Recommended**)

Filename: cp062161.compsig; cp062161.zip

Important Note!

This component is intended to be used by HPE applications. It is a zip file that contains the same driver deliverable available from the vmware.com and the HPE vibsdepot.hpe.com webpages, plus an HPE specific CP0xxxxx.xml file.

HPE recommends the firmware provided in *HPE Intel Online Firmware Upgrade Utility for VMware*, version 3.24.0 or later, for use with this driver.

Enhancements

This product added support to new Gen11 servers.

Supported Devices and Features

These drivers support the following network adapters:

- HPE Ethernet 1Gb 2-port 361T Adapter
- HPE Ethernet 1Gb 2-port 361i Adapter
- HPE Ethernet 1Gb 2-port 363i Adapter
- HPE Ethernet 1Gb 4-port 366FLR Adapter
- HPE Ethernet 1Gb 4-port 366T Adapter

HPE Ethernet 1Gb 4-port 366i Adapter

- HPE Ethernet 1Gb 4-port 366i Communication Board
- Intel I350-T4 Ethernet 1Gb 4-port BASE-T Adapter for HPE
- Intel I350-T4 Ethernet 1Gb 4-port BASE-T OCP3 Adapter for HPE
- Intel(R) I350 Gigabit Network Connection

HPE Intel ixgben Driver for VMware vSphere 8.0

Version: 2024.03.00 (**Recommended**)

Filename: cp058394.compsig; cp058394.zip

Important Note!

This component is intended to be used by HPE applications. It is a zip file that contains the same driver deliverable available from the vmware.com and the HPE vibsdepot.hpe.com webpages, plus an HPE specific CP0xxxxx.xml file.

HPE recommends the firmware provided in *HPE Intel Online Firmware Upgrade Utility for VMware*, version 3.23.0 or later, for use with this driver.

Enhancements

This product enhanced the compatibility with firmware of Fortville 9.4.

Supported Devices and Features

These drivers support the following network adapters:

- HPE Ethernet 10Gb 2-port 560SFP+ Adapter
- HPE Ethernet 10Gb 2-port 560FLR-SFP+ Adapter
- HPE Ethernet 10Gb 2-port 561T Adapter
- HPE Ethernet 10Gb 2-port 561FLR-T Adapter
- HPE Ethernet 10Gb 2-port 562T Adapter
- HPE Ethernet 10Gb 2-port 562FLR-T Adapter

HPE QLogic FastLinQ 10/25/50 GbE Multifunction Driver for VMware vSphere 8.0

Version: 2024.09.00 (**Recommended**)

Filename: cp061739.compsig; cp061739.zip

Important Note!

This component is intended to be used by HPE applications. It is a zip file that contains the same driver deliverable available from the vmware.com and the HPE vibsdepot.hpe.com webpages, plus an HPE specific CP0xxxxx.xml file.

HPE recommends the firmware provided as below for use with these drivers,

- HPE QLogic FastLinQ Firmware Package for Arrowhead adapters, version 8.65.14 or later.
- HPE QLogic FastLinQ Online Firmware Upgrade Utility for VMware, version 4.19.0 or later.

Fixes

This product corrects an issue which system crashed due to hardware error.

Supported Devices and Features

This product supports the following network adapters:

- HPE Ethernet 10Gb 2-port 521T Adapter
 - HPE Ethernet 10Gb 2-port 524SFP+ Adapter
 - HPE Ethernet 10/25Gb 2-port 621SFP28 Adapter
 - HPE Ethernet 10/25Gb 2-port 622FLR-SFP28 Converged Network Adapter
 - HPE StoreFabric CN1200R-T Converged Network Adapter
 - HPE StoreFabric CN1300R Converged Network Adapter
 - HPE Ethernet 10/25Gb 2-port SFP28 QL41232HVCU OCP3 Adapter
 - HPE Ethernet 10/25Gb 2-port SFP28 QL41232HLCU Adapter
 - HPE Ethernet 10Gb 4-port SFP+ QL41134HLCU Adapter
 - HPE Ethernet 10Gb 2-port BaseT QL41132HLRJ Adapter
 - HPE Ethernet 10Gb 2-port BaseT QL41132HQRJ OCP3 Adapter
 - HPE Ethernet 10Gb 2-port SFP+ QL41132HVCU OCP3 Adapter
 - HPE Ethernet 10Gb 2-port SFP+ QL41132HLCU Adapter
-

HPE QLogic NX2 10/20 GbE Multifunction Driver for VMware vSphere 8.0
Version: 2024.09.00 **(Recommended)**
Filename: cp061741.compsig; cp061741.zip

Important Note!

This component is intended to be used by HPE applications. It is a zip file that contains the same driver deliverable available from the vmware.com and the HPE vibsdepot.hpe.com webpages, plus an HPE specific CP0xxxxx.xml file.

HPE recommends the firmware provided in *HPE QLogic NX2 Online Firmware Upgrade Utility for VMware*, version 1.35.0 or later, for use with this driver.

Fixes

- This product corrects an issue which fix TSO (TCP Segmentation Offload) issue when single segment is larger than pkt length.
- This product corrects an issue which PSOD while freeing DMA during 'esxcli qlfastlinc qcc' command execution.

Supported Devices and Features

These drivers support the following network adapters:

- HPE Ethernet 10Gb 2-port 530T Adapter
- HPE Ethernet 10Gb 2-port 530SFP+ Adapter
- HPE FlexFabric 10Gb 2-port 533FLR-T Adapter
- HPE FlexFabric 10Gb 2-port 534FLR-SFP+ Adapter
- HPE FlexFabric 10Gb 4-port 536FLR-T Adapter

Intel icen Driver for VMware vSphere 8.0
Version: 2024.09.00 **(Recommended)**
Filename: cp061668.compsig; cp061668.zip

Important Note!

- This component is intended to be used by HPE applications. It is a zip file that contains the same driver deliverable available from the vmware.com and the HPE vibsdepot.hpe.com webpages, plus an HPE specific CP0xxxxx.xml file.
- HPE recommends the firmware provided in *Intel Firmware Package For E810 Ethernet Adapter*, version 4.50 or later, for use with these drivers.

Fixes

This product fixed an issue which NIC port was in autonegotiation mode, many DOWN/UP sequences was applied by the link partner, and NIC port remained in DOWN state randomly.

Enhancements

This product added a warning message when RDMA critical error occurs.

Supported Devices and Features

This product supports the following network adapters:

- Intel E810-CQDA2 Ethernet 100Gb 2-port QSFP28 Adapter for HPE
- Intel E810-CQDA2 Ethernet 100Gb 2-port QSFP28 OCP3 Adapter for HPE
- Intel E810-XXVDA4 Ethernet 10/25Gb 4-port SFP28 Adapter for HPE
- Intel E810-XXVDA2 Ethernet 10/25Gb 2-port SFP28 Adapter for HPE
- Intel E810-XXVDA2 Ethernet 10/25Gb 2-port SFP28 OCP3 Adapter for HPE
- Intel E810-2CQDA2 Ethernet 100Gb 2-port QSFP28 Adapter for HPE
- Intel E810-XXVDA4 Ethernet 10/25Gb 4-port SFP28 OCP3 Adapter for HPE

Driver - Storage Controller

HPE MR416i-p, MR416i-o, MR216i-o, MR408i-o, MR216i-p Gen10P and Gen11 controller (64-bit) Driver for vSphere 8.0
Version: 2023.12.01 **(Recommended)**
Filename: cp057484.compsig; cp057484.zip

[Top](#)

Important Note!

- This component is intended to be used by HPE applications. It is a zip that contains the same driver deliverable available from the vmware.com and the HPE vibsdepot.hpe.com webpages, plus an HPE specific CPXXXX.xml file.

Enhancements

- New release for version 7.726.02.00.
- This new 7.26 release have not completed vSAN certification, please don't update for vSAN environment for now. Target to complete vSAN certification by end of February 2024.
- Support new HPE ProLiant DL145 Gen11 server.

HPE ProLiant Gen10 Smart Array and Gen10 Plus and Gen11 Smart RAID Controller Driver for VMware vSphere 8.0 (Driver Component).
Version: 2024.10.01 **(Recommended)**
Filename: cp059502.compsig; cp059502.zip

Important Note!

- This component is intended to be used by HPE applications. It is a zip that contains the same driver deliverable available from the vmware.com, plus an HPE specific CPXXXX.xml file.
- Actual ESXi Version is 80.4672.0.104

Fixes

- Fixed an issue where a PSOD occurred during array delete operations.
- Fixed an issue where failed logical volumes take too long to be removed at the OS level.
- Fixed an issue where NVMe drives were not discovered after hot-plug operation.
- Fixed a potential data loss risk for SmartCache Logical Drives configured in WriteBack mode during shutdown.

Firmware - Network

Broadcom Firmware Package for BCM5741x adapters
Version: 230.1.123.0 **(Recommended)**
Filename: bcm230.1.123.0.pup.fwpkg

[Top](#)

Important Note!

For Firmware installation, there is no OS and drivers dependency.

For Firmware compatibility during production, HPE recommends the drivers for use with the firmware Package product as below,

- Broadcom NetXtreme-E Driver for Microsoft Windows Server, version 230.0.162.0 or later
- HPE Broadcom NetXtreme-E Drivers for Linux, version 1.10.3-230.0.132.0 or later
- HPE Broadcom NetXtreme-E Drivers for VMware, version 2024.09.00 or later

Fixes

- This product addresses an issue where getting Transceiver Temperature erroneous unit value.
- This product addresses an issue when NC-SI Query Pending NC PLDM Response is wrong when NIC does not have a pending PLDM request.
- The product addresses an issue where temperature error messages exceed critical values as seen in the Redfish Device Enablement (RDE) Ports schema when the LinkState is set to Disabled.

Enhancements

- This product enhances the Get Package Status command support.
- This product enhances to add a warning message when a non-supported dual-rate transceiver is used.
- This product enhances the Addition of SFF 8472 Transceiver Power Details to RDE Port Metrics.

Supported Devices and Features

This product supports the following network adapters:

- HPE Ethernet 10Gb 2-port SFP+ BCM57412 Adapter
- HPE Ethernet 10Gb 2-port SFP+ BCM57412 OCP3 Adapter
- HPE Ethernet 10Gb 2-port BaseT BCM57416 Adapter
- HPE Ethernet 10Gb 2-port BaseT BCM57416 OCP3 Adapter
- HPE Ethernet 10/25Gb 2-port SFP28 BCM57414 Adapter
- HPE Ethernet 10/25Gb 2-port SFP28 BCM57414 OCP3 Adapter

Broadcom Firmware Package for BCM5750x adapters
Version: 230.1.123.0 **(Recommended)**
Filename: bcm230.1.123.0_Thor.pup.fwpkg

Important Note!

For Firmware installation, there is no OS and drivers dependency.

For Firmware compatibility during production, HPE recommends the drivers for use with the firmware Package product as below,

- Broadcom NetXtreme-E Driver for Microsoft Windows Server, version 230.0.162.0 or later
- HPE Broadcom NetXtreme-E Drivers for Linux, version 1.10.3-230.0.132.0 or later
- HPE Broadcom NetXtreme-E Drivers for VMware, version 2024.09.00 or later

Fixes

- This product addresses an issue where RDE Port LLDPReceive ManagementAddressMAC returned empty string when it's not present.
- This product addresses an issue where Ethtool shows wrong module type when a port is in a certain breakout mode.
- This product addresses an issue where in low temperature test, BMC reading module temperature result is 0xff.
- This product addresses an issue where failure to set default values for firmware speed capabilities.
- This product enhances support for loopback port statistics via HWRM (Hardware Resource Manager).
- This product addresses an issue where flow control status in dmesg shows wrong TX and RX negotiated status.
- This product addresses an issue where fixed bnxtnvm to verify the VPD data before writing to the NVM.
- This product addresses an issue where ping failures between allmulticast enabled VFs.
- This product addresses where the RoCE protocol's read_context function in the HWRM (Hardware Resource Manager) component was failing when dealing with the Completion Queue.

Enhancements

- This product enhances the core-dump missing a few entries.
- This product enhances the Hardware CoS queue re-configuration between ifdown/ifup.
- This product enhances to add support for enable/disable RDMA to NCSI command NcsiCmd_Set_Partition_Cfg_cmd function.
- This product enhances to add support store PLDM Monitoring and Control events before BMC's SetEventReceiver command.
- This product addresses an issue where Tx timeout detected in dmesg while running L2 traffic with 9600 MTU.

Supported Devices and Features

This product supports the following network adapters:

- Broadcom BCM57504 Ethernet 10/25Gb 4-port SFP28 Adapter for HPE
- Broadcom BCM57504 Ethernet 10/25Gb 4-port SFP28 OCP3 Adapter for HPE

Broadcom NX1 Online Firmware Upgrade Utility for VMware

Version: 1.39.0 (**Recommended**)

Filename: CP062085.compsig; CP062085.zip

Important Note!

This software package contains combo image v20.30.41 with the following firmware versions:

| NIC | Boot Code Version | PXE Version | NCSI Version | UEFI Version |
|------------------------------------|--------------------------|--------------------|---------------------|---------------------|
| BCM 5719 1GbE 4p BASE-T Adptr | 1.55 | 21.6.4 | 1.5.55 | 21.6.74 |
| BCM 5719 1GbE 4p BASE-T OCP3 Adptr | 1.55 | 21.6.4 | 1.5.55 | 21.6.74 |
| BCM 5719 1GbE 4p BASE-T LOM Adptr | 1.55 | 21.6.4 | 1.5.55 | 21.6.74 |
| BCM 5720 1GbE 2p BASE-T LOM Adptr | 1.43 | 21.6.4 | 1.5.55 | 21.6.74 |

Prerequisites

This product requires the appropriate driver for your device and operating system to be installed before the firmware is updated.

Fixes

- This product addresses a problem that might cause a BSOD when trying to reboot the system from operating Windows systems due to NIC internal software mutex problem.
- This product addresses an issue where a random missing DHCP IP address occurs when the iLO shared NIC port is used, due to NIC internal software mutex problem.
- This product addresses an issue that might cause the POST to get stuck due to NIC internal software mutex problem.

Supported Devices and Features

This product supports the following network adapters:

- Broadcom BCM5720 Ethernet 1Gb 2-port BASE-T LOM Adapter for HPE
- Broadcom BCM5719 Ethernet 1Gb 4-port Base-T Adapter for HPE
- Broadcom BCM5719 Ethernet 1Gb 4-port Base-T OCP3 Adapter for HPE
- Broadcom BCM5719 Ethernet 1Gb 4-port Base-T LOM Adapter for HPE

HPE Broadcom NetXtreme-E Online Firmware Upgrade Utility for VMware

Version: 5.23.0 (**Recommended**)

Filename: CP062108.compsig; CP062108.zip

Important Note!

HPE recommends *HPE Broadcom NetXtreme-E Drivers for VMware*, versions 2024.09.00 or later, for use with this firmware.

This software package contains NVM Image version 230.1.123000 with the following firmware versions:

| NIC | Bootcode Version | NCSI Version | MBA Version | UEFI Version | RoCE Version |
|--|------------------|--------------|-------------|--------------|--------------|
| HPE Ethernet 10Gb 2-port 535FLR-T Adapter | 230.0.168.0 | 230.0.168.0 | 230.0.167.0 | 230.0.167.0 | 230.0.168.0 |
| HPE Ethernet 10Gb 2-port 535T Adapter | | | | | |
| HPE Ethernet 10/25Gb 2-port 631FLR-SFP28 Adapter | | | | | |
| HPE Ethernet 10/25Gb 2-port 631SFP28 Adapter | | | | | |
| HPE Ethernet 10Gb 2-port 537SFP+ Adapter | | | | | |
| HPE Ethernet 10Gb 2-port 537SFP+ FLR Adapter | | | | | |

Prerequisites

This product requires the appropriate driver for your device and operating system be installed before firmware is updated.

Fixes

- This product addresses an issue where getting Transceiver Temperature erroneous unit value.
- This product addresses an issue when NC-SI Query Pending NC PLDM Response is wrong when NIC does not have a pending PLDM request.

Enhancements

- This product enhances the Get Package Status command support.
- This product enhances to add a warning message when a non-supported dual-rate transceiver is used.
- This product enhances the Addition of SFF 8472 Transceiver Power Details to RDE Port Metrics.

Supported Devices and Features

This product supports the following network adapters:

- HPE Ethernet 10Gb 2-port 537SFP+ Adapter
- HPE Ethernet 10Gb 2-port 537SFP+ FLR Adapter
- HPE Ethernet 10Gb 2-port 535T Adapter
- HPE Ethernet 10Gb 2-port 535FLR-T Adapter
- HPE Ethernet 10/25Gb 2-port 631SFP28 Adapter
- HPE Ethernet 10/25Gb 2-port 631FLR-SFP28 Adapter

HPE Broadcom NX1 Online Firmware Upgrade Utility VMware for HPE ProLiant Gen10 server series Only.

Version: 1.39.0 (**Recommended**)

Filename: CP062096.compsig; CP062096.zip

Important Note!

- **This component ONLY support HPE ProLiant Gen10 server series.**

This software package contains combo image v20.30.41 with the following firmware versions:

| NIC | Boot Code Version | PXE Version | NCSI Version | UEFI Version |
|---|-------------------|-------------|--------------|--------------|
| HPE Ethernet 1Gb 2-port 330i Adapter (22BD) | 2.10 | 21.6.4 | 1.5.55 | 21.6.74 |
| HPE Ethernet 1Gb 4-port 331i Adapter (22BE) HPE Ethernet 1Gb 4-port 331FLR Adapter HPE Ethernet 1Gb 4-port 331T Adapter | 1.55 | 21.6.4 | 1.5.55 | 21.6.74 |
| HPE Ethernet 1Gb 2-port 332i Adapter (22E8) HPE Ethernet 1Gb 2-port 332T Adapter | 1.43 | 21.6.4 | 1.5.55 | 21.6.74 |

For previous firmware versions prior to v20.19.51, please refer to the link : <https://www.hpe.com/global/swpublishing/MTX-4f19da2bceff4b73a31531d71e>

Prerequisites

This product requires the appropriate driver for your device and operating system be installed before firmware is updated.

Enhancements

This product enhances NVRAM configuration during the firmware upgrade.

Supported Devices and Features

This product supports the following network adapters:

- HPE Ethernet 1Gb 2-port 330i Adapter (22BD)
- HPE Ethernet 1Gb 4-port 331i Adapter (22BE)
- HPE Ethernet 1Gb 4-port 331FLR Adapter
- HPE Ethernet 1Gb 4-port 331T Adapter
- HPE Ethernet 1Gb 2-port 332i Adapter (22E8)
- HPE Ethernet 1Gb 2-port 332T Adapter

HPE Intel Online Firmware Upgrade Utility VMware for HPE ProLiant Gen9 and Gen10 server series Only.

Version: 3.24.0 (**Recommended**)

Filename: CP061687.compsig; CP061687.zip

Important Note!

- This software package contains the following firmware versions for the below listed supported network adapters:

| NIC | EEPROM/NVM Version | OROM Version | Single NVM Version |
|--|--------------------|--------------|--------------------|
| HPE Ethernet 1Gb 2-port 361i Adapter | 8000119A | 1.3612.0 | N/A |
| HPE Ethernet 1Gb 2-port 361T Adapter | 80001147 | 1.3612.0 | N/A |
| HPE Ethernet 1Gb 4-port 366FLR Adapter | 800011A1 | 1.3612.0 | N/A |
| HPE Ethernet 1Gb 4-port 366T Adapter | 800011F1 | 1.3612.0 | N/A |
| HPE Ethernet 1Gb 2-port 368i Adapter | 80003AC5 | 1.3612.0 | N/A |
| HPE Ethernet 1Gb 2-port 368FLR-MMT Adapter | 80003AC2 | 1.3612.0 | N/A |
| HPE Ethernet 1Gb 4-port 369i Adapter | 80003AC3 | 1.3612.0 | N/A |
| HPE Ethernet 10Gb 2-port 568i Adapter | 80003AC4 | 1.3612.0 | N/A |
| HPE Ethernet 10Gb 2-port 568FLR-MMSFP+ Adapter | 80003AC2 | 1.3612.0 | N/A |
| HPE Ethernet 10Gb 2-port 568FLR-MMT Adapter | 80003AC2 | 1.3612.0 | N/A |
| HPE Ethernet 10Gb 2-port 563i Adapter | 800035C0 | 1.1375.0 | N/A |
| HPE Ethernet 10Gb 2-port 562FLR-SFP+ Adapter | 8000F231 | 1.3612.0 | 11.1.7 |

| | | | |
|---|----------|----------|---------|
| HPE Ethernet 10Gb 2-port 562FLR-T Adapter | 800016F1 | 1.3612.0 | 10.55.3 |
| HPE Ethernet 10Gb 2-port 562SFP+ Adapter | 8000F232 | 1.3612.0 | 11.1.7 |
| HPE Ethernet 10Gb 2-port 562T Adapter | 800016EF | 1.3612.0 | 10.55.3 |

The combo image v1.3612.0 includes: Boot Agent: 1GbE - v1.5.90, 10GbE - v2.4.54, 40GbE - v1.1.45 & UEFI Drivers: 1GbE - v9.8.52, 10GbE - v8.2.46, 40GbE - v5.0.04

Single NVM Version is new firmware format which represent an unified version in place of the previously used EEPROM/NVM Version or OROM version.

This software package no longer contains Firmware for the below listed supported network adapters:

HPE Ethernet 1Gb 2-port 363i Adapter

HPE Ethernet 1Gb 4-port 366i Adapter

HPE Ethernet 1Gb 4-port 366i Communication Board

HPE Ethernet 10Gb 2-port 560FLR-SFP+ Adapter

HPE Ethernet 10Gb 2-port 560SFP+ Adapter

HPE Ethernet 10Gb 2-port 561FLR-T Adapter

HPE Ethernet 10Gb 2-port 561T Adapter

- The latest firmware version of above adapters, please refer to the link : https://support.hpe.com/connect/s/softwaredetails?language=en_US&softwareId=MTX_d7826493bb5a4aa69b4aa9a1d5&tab=releaseNotes

Prerequisites

This product requires the appropriate driver for your device and operating system be installed before firmware is updated.

Enhancements

This product enhanced the compatibility with the latest drivers.

Supported Devices and Features

This package supports the following network adapters:

- HPE Ethernet 1Gb 2-port 361i Adapter
- HPE Ethernet 1Gb 2-port 361T Adapter
- HPE Ethernet 1Gb 2-port 368FLR-MMT Adapter
- HPE Ethernet 1Gb 2-port 368i Adapter
- HPE Ethernet 1Gb 4-port 366FLR Adapter
- HPE Ethernet 1Gb 4-port 366T Adapter
- HPE Ethernet 1Gb 4-port 369i Adapter
- HPE Ethernet 10Gb 2-port 562FLR-SFP+ Adapter
- HPE Ethernet 10Gb 2-port 562FLR-T Adapter
- HPE Ethernet 10Gb 2-port 562SFP+ Adapter
- HPE Ethernet 10Gb 2-port 562T Adapter
- HPE Ethernet 10Gb 2-port 568FLR-MMSFP+ Adapter
- HPE Ethernet 10Gb 2-port 568FLR-MMT Adapter
- HPE Ethernet 10Gb 2-port 568i Adapter
- HPE Ethernet 10Gb 2-port 563i Adapter

HPE QLogic FastLinQ Firmware Package for Arrowhead adapters

Version: 8.65.14 (**Recommended**)

Filename: ql_hp_ah_mbi_8.65.14_pldm.fwpkg

Important Note!

For Firmware installation, there is no OS and drivers dependency.

For Firmware compatibility during production, HPE recommends the drivers for use with the firmware Package product as below,

- HPE QLogic FastLinQ 10/25/50 GbE Drivers for Linux, version 8.74.4.0-8 or later
- HPE QLogic FastLinQ 10/25/50 GbE Drivers for Microsoft Windows Server x64 Editions, version 8.72.15.0 or later
- HPE QLogic FastLinQ 10/25/50 GbE Multifunction Drivers for VMware, version 2024.09.00 or later

This software package contains combo image v8.65.14. This combo image includes: Boot Code (MFW): 8.65.5.0, PXE:2.0.19, and UEFI: 4.1.13.1.

Enhancements

This product enhanced the compatibility with drivers.

Supported Devices and Features

This product supports the following network adapters:

- HPE Ethernet 10Gb 2-port 521T Adapter
- HPE Ethernet 10Gb 2-port 524SFP+ Adapter
- HPE Ethernet 10/25Gb 2-port 621SFP28 Adapter
- HPE Ethernet 10/25Gb 2-port 622FLR-SFP28 Adapter
- HPE StoreFabric CN1200R-T Converged Network Adapter
- HPE StoreFabric CN1300R Converged Network Adapter

HPE QLogic FastLinQ Online Firmware Upgrade Utility for VMware

Version: 4.19.0 (**Recommended**)

Filename: CP061755.compsig; CP061755.zip

Important Note!

HPE recommends *HPE QLogic FastLinQ 10/25/50GbE Multifunction Drivers for VMware*, versions 2024.09.00 or later, for use with this firmware.

This software package contains combo image version v8.65.14 includes:

- Boot Code (MFW): 8.65.5.0
- UEFI: 4.1.13.1
- PXE: 2.0.19

The users will only see the combo image versions in the interactive mode firmware update or while using HPSUM/SPP to update the firmware on the supported adapters.

Prerequisites

This product requires the appropriate driver for your device and operating system be installed before firmware is updated.

Enhancements

This product enhanced the compatibility with drivers.

Supported Devices and Features

This product supports the following network adapters:

- HPE Ethernet 10Gb 2-port 521T Adapter
- HPE Ethernet 10Gb 2-port 524SFP+ Adapter
- HPE Ethernet 10/25Gb 2-port 621SFP28 Adapter
- HPE Ethernet 10/25Gb 2-port 622FLR-SFP28 Converged Network Adapter
- HPE StoreFabric CN1200R-T Converged Network Adapter
- HPE StoreFabric CN1300R Converged Network Adapter

HPE QLogic NX2 Online Firmware Upgrade Utility for VMware

Version: 1.35.0 (**Recommended**)

Filename: CP061753.compsig; CP061753.zip

Important Note!

HPE recommends *HPE QLogic NX2 10/20GbE Multifunction Drivers for VMware*, versions 2024.09.00 or later, for use with this firmware.

This software package contains combo image v7.19.27 with the following firmware versions:

| NIC | Boot Code Version | PXE Version | UEFI Version | iSCSI Version | FCoE Version | CCM Version | L2 Version |
|----------------------------------|-------------------|-------------|--------------|---------------|--------------|-------------|------------|
| HPE Ethernet 10Gb 2-port 530SFP+ | | | | | | | |

| | | | | | | | |
|--|---------|---------|-------|--------|--------|--------|---------|
| Adapter HPE Ethernet 10Gb 2-port 530T Adapter | 7.16.15 | 7.14.13 | 8.9.3 | n/a | n/a | 7.14.4 | 7.12.25 |
| HPE Ethernet 10Gb 2-port 533FLR-T Adapter HPE FlexFabric 10Gb 2-port 534FLR- SFP+ Adapter HPE FlexFabric 10Gb 4-port 536FLR-T Adapter | 7.16.15 | 7.14.13 | 8.9.3 | 7.14.0 | 7.14.3 | 7.14.4 | 7.12.25 |

Prerequisites

This product requires the appropriate driver for your device and operating system be installed before firmware is updated.

Enhancements

This product enhanced the compatibility with drivers.

Supported Devices and Features

This product supports the following network adapters:

- HPE Ethernet 10Gb 2-port 530SFP+ Adapter
- HPE Ethernet 10Gb 2-port 530T Adapter
- HPE Ethernet 10Gb 2-port 533FLR-T Adapter
- HPE FlexFabric 10Gb 2-port 534FLR-SFP+ Adapter
- HPE FlexFabric 10Gb 4-port 536FLR-T Adapter

Intel Firmware Package For E810-2CQDA2 Ethernet 100Gb 2-port QSFP28 Adapter

Version: 4.50 (**Recommended**)

Filename: HPE_E810_2CQDA2_O_SEC_4p50_PLDMoMCTP_8001D8B4.fwpkg

Important Note!

For Firmware installation, there is no OS and drivers dependency.

For Firmware compatibility during production, HPE recommends the drivers for use with the firmware Package product as below,

- Intel ica Driver for Microsoft Windows Server, version 1.15.121.0 or later
- Intel ice Drivers for Linux, version 1.14.11-1 or later
- Intel icen Driver for VMware, version 2024.09.00 or later

This FW version does not support Port.Reset RDE metrics. This product will be enhance to improve the functions in the future release

Fixes

- This product addressed an issue where Network Interface initialization failure under OS or Firmware rollback may be seen with LLDP enabled.
- This product addressed an issue where RDE PermanentMACAddress changes simultaneously when send PATCH request for MACAddress property with Firmware 4.30.

Supported Devices and Features

This product supports the following network adapters:

- Intel E810-2CQDA2 Ethernet 100Gb 2-port QSFP28 Adapter for HPE

Intel Firmware Package For E810-CQDA2 Ethernet 100Gb 2-port QSFP28 Adapter

Version: 4.50 (**Recommended**)

Filename: HPE_E810_CQDA2_4p50_PLDMoMCTP_8001D8B6.fwpkg

Important Note!

For Firmware installation, there is no OS and drivers dependency.

For Firmware compatibility during production, HPE recommends the drivers for use with the firmware Package product as below,

- Intel ica Driver for Microsoft Windows Server, version 1.15.121.0 or later
- Intel ice Drivers for Linux, version 1.14.11-1 or later
- Intel icen Driver for VMware, version 2024.09.00 or later

This FW version does not support Port.Reset RDE metrics. This product will be enhance to improve the functions in the future release

Fixes

- This product addressed an issue where Network Interface initialization failure under OS or Firmware rollback may be seen with LLDP enabled.
- This product addressed an issue where RDE PermanentMACAddress changes simultaneously when send PATCH request for MACAddress property with Firmware 4.30.

Supported Devices and Features

This product supports the following network adapters:

- Intel E810-CQDA2 Ethernet 100Gb 2-port QSFP28 Adapter for HPE

Intel Firmware Package For E810-CQDA2 Ethernet 100Gb 2-port QSFP28 OCP3 Adapter

Version: 4.50 (**Recommended**)

Filename: HPE_E810_CQDA2_OCP_4p50_NCSIwPLDMoMCTP_8001D8BC.fwpkg

Important Note!

For Firmware installation, there is no OS and drivers dependency.

For Firmware compatibility during production, HPE recommends the drivers for use with the firmware Package product as below,

- Intel ica Driver for Microsoft Windows Server, version 1.15.121.0 or later
- Intel ice Drivers for Linux, version 1.14.11-1 or later
- Intel icen Driver for VMware, version 2024.09.00 or later

This FW version does not support Port.Reset RDE metrics. This product will be enhance to improve the functions in the future release

Fixes

- This product addressed an issue where Network Interface initialization failure under OS or Firmware rollback may be seen with LLDP enabled.
- This product addressed an issue where RDE PermanentMACAddress changes simultaneously when send PATCH request for MACAddress property with Firmware 4.30.

Supported Devices and Features

This product supports the following network adapters:

- Intel E810-CQDA2 Ethernet 100Gb 2-port QSFP28 OCP3 Adapter for HPE

Intel Firmware Package For E810-XXVDA2 Ethernet 10/25Gb 2-port SFP28 Adapter

Version: 4.50 (**Recommended**)

Filename: HPE_E810_XXVDA2_SD_4p50_PLDMoMCTP_8001D8BA.fwpkg

Important Note!

For Firmware installation, there is no OS and drivers dependency.

For Firmware compatibility during production, HPE recommends the drivers for use with the firmware Package product as below,

- Intel ica Driver for Microsoft Windows Server, version 1.15.121.0 or later
- Intel ice Drivers for Linux, version 1.14.11-1 or later
- Intel icen Driver for VMware, version 2024.09.00 or later

This FW version does not support Port.Reset RDE metrics. This product will be enhance to improve the functions in the future release

Fixes

- This product addressed an issue where Network Interface initialization failure under OS or Firmware rollback may be seen with LLDP enabled.
- This product addressed an issue where RDE PermanentMACAddress changes simultaneously when send PATCH request for MACAddress property with Firmware 4.30.

Supported Devices and Features

This product supports the following network adapters:

- Intel E810-XXVDA2 Ethernet 10/25Gb 2-port SFP28 Adapter for HPE

Intel Firmware Package For E810-XXVDA2 Ethernet 10/25Gb 2-port SFP28 OCP3 Adapter

Version: 4.50 (**Recommended**)

Filename: HPE_E810_XXVDA2_SD_OCP_4p50_NCSIwPLDMoMCTP_8001D8B3.fwpkg

Important Note!

For Firmware installation, there is no OS and drivers dependency.

For Firmware compatibility during production, HPE recommends the drivers for use with the firmware Package product as below,

- Intel ica Driver for Microsoft Windows Server, version 1.15.121.0 or later
- Intel ice Drivers for Linux, version 1.14.11-1 or later
- Intel icen Driver for VMware, version 2024.09.00 or later

This FW version does not support Port.Reset RDE metrics. This product will be enhance to improve the functions in the future release

Fixes

- This product addressed an issue where Network Interface initialization failure under OS or Firmware rollback may be seen with LLDP enabled.
- This product addressed an issue where RDE PermanentMACAddress changes simultaneously when send PATCH request for MACAddress property with Firmware 4.30.

Supported Devices and Features

This product supports the following network adapters:

- Intel E810-XXVDA2 Ethernet 10/25Gb 2-port SFP28 OCP3 Adapter for HPE

Intel Firmware Package For E810-XXVDA4 Ethernet 10/25Gb 4-port SFP28 Adapter

Version: 4.50 (**Recommended**)

Filename: HPE_E810_XXVDA4_FH_4p50_PLDMoMCTP_8001D8B5.fwpkg

Important Note!

For Firmware installation, there is no OS and drivers dependency.

For Firmware compatibility during production, HPE recommends the drivers for use with the firmware Package product as below,

- Intel ica Driver for Microsoft Windows Server, version 1.15.121.0 or later
- Intel ice Drivers for Linux, version 1.14.11-1 or later
- Intel icen Driver for VMware, version 2024.09.00 or later

This FW version does not support Port.Reset RDE metrics. This product will be enhance to improve the functions in the future release

Fixes

- This product addressed an issue where Network Interface initialization failure under OS or Firmware rollback may be seen with LLDP enabled.
- This product addressed an issue where RDE PermanentMACAddress changes simultaneously when send PATCH request for MACAddress property with Firmware 4.30.
- This product addressed an issue where data is interchanged of Port 1 and Port 4 when running a Redfish GET Operation under the NetworkAdapter, NetworkDeviceFunctions and Port Schema with "Metrics" properties.

Supported Devices and Features

This product supports the following network adapters:

- Intel E810-XXVDA4 Ethernet 10/25Gb 4-port SFP28 Adapter for HPE

Intel Firmware Package For E810-XXVDA4 Ethernet 10/25Gb 4-port SFP28 OCP3 Adapter
Version: 4.50 (B) (**Recommended**)
Filename: HPE_E810_XXV4_OCP_4p50_NCSIwPLDMoMCTP_8001D8B8.fwpkg

Important Note!

For Firmware installation, there is no OS and drivers dependency.
For Firmware compatibility during production, HPE recommends the drivers for use with the firmware Package product as below,

- Intel ica Driver for Microsoft Windows Server, version 1.15.121.0 or later
- Intel ice Drivers for Linux, version 1.14.11-1 or later
- Intel icen Driver for VMware, version 2024.09.00 or later

This FW version does not support Port.Reset RDE metrics. This product will be enhance to improve the functions in the future release

Fixes

- This product addressed an issue where Network Interface initialization failure under OS or Firmware rollback may be seen with LLDP enabled.
- This product addressed an issue where RDE PermanentMACAddress changes simultaneously when send PATCH request for MACAddress property with Firmware 4.30.
- This product addressed an issue where data is interchanged of Port 1 and Port 4 when running a Redfish GET Operation under the NetworkAdapter, NetworkDeviceFunctions and Port Schema with "Metrics" properties.

Supported Devices and Features

This product supports the following network adapters:

- Intel E810-XXVDA4 Ethernet 10/25Gb 4-port SFP28 OCP3 Adapter for HPE

Intel Online Firmware Upgrade Utility for VMware
Version: 3.24.0 (**Recommended**)
Filename: CP061688.compsig; CP061688.zip

Important Note!

This software package contains the following firmware versions for the below listed supported network adapters:

| NIC | EEPROM/NVM Version | OROM Version | NVM Version |
|---|--------------------|--------------|-------------|
| HPE Ethernet 10Gb 2-port SFP+ OCP3 X710-DA2 Adapter | 8000F134 | 1.3602.0 | 9.50 |
| HPE Ethernet 10Gb 2-port SFP+ X710-DA2 Adapter | 8000F13D | 1.3602.0 | 9.50 |
| Intel I350-T4 Ethernet 1Gb 4-port BASE-T Adapter | 800011F8 | 1.3602.0 | N/A |
| Intel I350-T4 Ethernet 1Gb 4-port BASE-T OCP3 Adapter | 80001234 | 1.3602.0 | N/A |
| Intel(R) I350 Gigabit Network Connection (2-port) | 8000119C | 1.3602.0 | N/A |
| Intel(R) I350 Gigabit Network Connection (4-port) | 8000119D | 1.3602.0 | N/A |

The combo image v1.3602.0 includes: Boot Agent: 1GbE - v1.5.90, 10GbE - v2.4.54, 40GbE - v1.1.45 & UEFI Drivers: 1GbE - v9.8.52, 10GbE - v8.2.46, 40GbE - v5.0.04

Single NVM Version is new firmware format which represent an unified version in place of the previously used EEPROM/NVM Version or OROM version.

Prerequisites

This product requires the appropriate driver for your device and operating system be installed before firmware is updated.

Enhancements

This product enhanced the compatibility with the latest drivers.

Supported Devices and Features

This package supports the following network adapters:

- Intel(R) I350 Gigabit Network Connection (2-port)
- Intel(R) I350 Gigabit Network Connection (4-port)
- HPE Ethernet 1Gb 4-port BaseT I350-T4 Adapter
- HPE Ethernet 1Gb 4-port BaseT I350-T4 OCP3 Adapter
- HPE Ethernet 10Gb 2-port SFP+ X710-DA2 OCP3 Adapter
- HPE Ethernet 10Gb 2-port SFP+ X710-DA2 Adapter

Marvell FastLinQ Firmware Package for Arrowhead adapters

Version: 8.65.14 (**Recommended**)

Filename: ql_ah_mbi_open_8.65.14_pldm.fwpkg

Important Note!

For Firmware installation, there is no OS and drivers dependency.

For Firmware compatibility during production, HPE recommends the drivers for use with the firmware Package product as below,

- Marvell FastLinQ 10/25/50 GbE Drivers for Microsoft Windows Server x64 Editions, version 8.72.15.0 or later
- HPE QLogic FastLinQ 10/25/50 GbE Drivers for Linux, version 8.74.4.0-8 or later
- HPE QLogic FastLinQ 10/25/50 GbE Multifunction Drivers for VMware, version 2024.09.00 or later

Enhancements

This product enhanced the compatibility with drivers.

Supported Devices and Features

This product supports the following network adapters:

- HPE Ethernet 10/25Gb 2-port SFP28 QL41232HLCU Adapter
- HPE Ethernet 10/25Gb 2-port SFP28 QL41232HVCU OCP3 Adapter
- HPE Ethernet 10Gb 2-port BaseT QL41132HLRJ Adapter
- HPE Ethernet 10Gb 2-port BaseT QL41132HQRJ OCP3 Adapter
- HPE Ethernet 10Gb 2-port SFP+ QL41132HLCU Adapter
- HPE Ethernet 10Gb 2-port SFP+ QL41132HVCU OCP3 Adapter
- HPE Ethernet 10Gb 4-port SFP+ QL41134HLCU Adapter

Marvell FastLinQ Online Firmware Upgrade Utility for VMware

Version: 8.55.12 (**Recommended**)

Filename: CP058235.compsig; CP058235.zip

Important Note!

This software package contains combo image v8.55.12. This combo image includes:

- PXE: 2.0.19
- Boot Code (MFW): 8.55.22.0
- UEFI: 6.1.8.2

Prerequisites

This product requires the appropriate driver for your device and operating system be installed before firmware is updated.

Fixes

- This product contains support PLDM firmware upgrade base improvements.
- This product addresses an overheat issue on the network adapters as below,

HPE Ethernet 10Gb 2-port BaseT QL41132HLRJ Adapter
HPE Ethernet 10Gb 2-port BaseT QL41132HQRJ OCP3 Adapter

Enhancements

This product now supported NPAR enabling option.

Supported Devices and Features

This product supports the following network adapters:

- HPE Ethernet 10/25Gb 2-port SFP28 QL41232HVCU OCP3 Adapter
- HPE Ethernet 10/25Gb 2-port SFP28 QL41232HLCU Adapter
- HPE Ethernet 10Gb 4-port SFP+ QL41134HLCU Adapter
- HPE Ethernet 10Gb 2-port BaseT QL41132HLRJ Adapter
- HPE Ethernet 10Gb 2-port BaseT QL41132HQRJ OCP3 Adapter
- HPE Ethernet 10Gb 2-port SFP+ QL41132HVCU OCP3 Adapter
- HPE Ethernet 10Gb 2-port SFP+ QL41132HLCU Adapter

Mellanox Firmware Package (FWPKG) - Mellanox MCX631102AS-ADAT Ethernet 10/25Gb 2-port SFP28 Adapter for HPE

Version: 26.41.1000 (**Recommended**)

Filename: 26_41_1000-MCX631102AS-ADA_Ax.pldm.fwpkg

Important Note!

Disclaimer: Certain software including drivers and documents may be available from NVIDIA. If you select a URL that directs you to <http://www.nvidia.com/>, you are then leaving HPE.com. Please follow the instructions on <http://www.nvidia.com/> to download NVIDIA software or documentation. When downloading the NVIDIA software or documentation, you may be subject to NVIDIA terms and conditions, including licensing terms, if any, provided on its website or otherwise. HPE is not responsible for your use of any software or documents that you download from <http://www.nvidia.com/>, except that HPE may provide a limited warranty for NVIDIA software in accordance with the terms and conditions of your purchase of the HPE product or solution.

A list of known issues with this release is available

at: <https://docs.nvidia.com/networking/display/connectx6lxfirmwarev26411000/known+issues>

Prerequisites

FWPKG will work only if the firmware version flashed on the adapter is 20.27.1016 or later and iLO5 firmware version must be 2.30 or higher.

Fixes

The following issues have been fixed in version 26.41.1000:

- Traffic failure occurred when modifying the VIRTIO_NET_F_MRG_RXBUF bit for the VDPA device during traffic.
- The second mkey index returned even if it was not set in the creation of the virtio q when querying virtio q object.
- Traffic loss occurred after performing Live Migration with virtio vq "frozen-ready" feature.

Note: When the traffic load is high, and the vq frozen-ready cap is on, traffic loss might still be experienced after modifying the vq from suspend to ready mode.

Enhancements

Security Hardening Enhancements: This release contains important reliability improvements and security hardening enhancements. HPE recommends upgrading your device's firmware to this release to improve the firmware security and reliability of your device.

New features and changes included in version 26.41.1000:

- Implemented Deterministic Random Bit Generator (DRBG) algorithm on top of firmware TRNG (the source for raw data input) in accordance with NIST SP800-90A.
- Added support for vDPA virtual queue state change from suspend to ready, and discrete mkey for descriptor. vDPA Live Migration uses these two new capabilities to reduce downtime since vq can go back to ready state for traffic and descriptor-only-mkey can help reduce mkey mapping time.
- Added a new NVConfig option to copy AR bit from the BTH header to the DHCP header.
- Added the option to provide field's offset and length in Steering add_action option.
- Added support for steering match on packet I4_type through FTG/FTE.
- Extended Flex Parser merge mechanism to support hardware capabilities.
- Enabled the option to disable the native parser when the parse graph node is configured with the same conditions.
- Added support for father/son headers parsing.
- Added support for tunnel_offload in LRO.

Supported Devices and Features

| HPE Part Number | Mellanox Ethernet Only Adapters | PSID |
|-----------------|---|---------------|
| P42044-B21 | Mellanox MCX631102AS-ADAT Ethernet 10/25Gb 2-port SFP28 Adapter for HPE | MT_0000000575 |

Mellanox Firmware Package (FWPKG) - Mellanox MCX631432AS-ADAI Ethernet 10/25Gb 2-port SFP28 OCP3 Adapter for HPE
Version: 26.41.1000 (**Recommended**)
Filename: 26_41_1000-MCX631432AS-ADA_Ax.pldm.fwpkg

Important Note!

Disclaimer: Certain software including drivers and documents may be available from NVIDIA. If you select a URL that directs you to <http://www.nvidia.com/>, you are then leaving HPE.com. Please follow the instructions on <http://www.nvidia.com/> to download NVIDIA software or documentation. When downloading the NVIDIA software or documentation, you may be subject to NVIDIA terms and conditions, including licensing terms, if any, provided on its website or otherwise. HPE is not responsible for your use of any software or documents that you download from <http://www.nvidia.com/>, except that HPE may provide a limited warranty for NVIDIA software in accordance with the terms and conditions of your purchase of the HPE product or solution.

A list of known issues with this release is available at: <https://docs.nvidia.com/networking/display/connectx6lxfirmwarev26411000/known+issues>

Prerequisites

FWPKG will work only if the firmware version flashed on the adapter is 20.27.1016 or later and iLO5 firmware version must be 2.30 or higher.

Fixes

The following issues have been fixed in version 26.41.1000:

- Traffic failure occurred when modifying the VIRTIO_NET_F_MRG_RXBUF bit for the VDPA device during traffic.
- The second mkey index returned even if it was not set in the creation of the virtio q when querying virtio q object.
- Traffic loss occurred after performing Live Migration with virtio vq "frozen-ready" feature.

Note: When the traffic load is high, and the vq frozen-ready cap is on, traffic loss might still be experienced after modifying the vq from suspend to ready mode.

Enhancements

Security Hardening Enhancements: This release contains important reliability improvements and security hardening enhancements. HPE recommends upgrading your device's firmware to this release to improve the firmware security and reliability of your device.

New features and changes included in version 26.41.1000:

- Implemented Deterministic Random Bit Generator (DRBG) algorithm on top of firmware TRNG (the source for raw data input) in accordance with NIST SP800-90A.
- Added support for vDPA virtual queue state change from suspend to ready, and discrete mkey for descriptor. vDPA Live Migration uses these two new capabilities to reduce downtime since vq can go back to ready state for traffic and descriptor-only-mkey can help reduce mkey mapping time.
- Added a new NVConfig option to copy AR bit from the BTH header to the DHCP header.
- Added the option to provide field's offset and length in Steering add_action option.
- Added support for steering match on packet I4_type through FTG/FTE.
- Extended Flex Parser merge mechanism to support hardware capabilities.
- Enabled the option to disable the native parser when the parse graph node is configured with the same conditions.
- Added support for father/son headers parsing.
- Added support for tunnel_offload in LRO.

Supported Devices and Features

| HPE Part Number | Mellanox Ethernet Only Adapters | PSID |
|-----------------|--|---------------|
| P42041-B21 | Mellanox MCX631432AS-ADAI Ethernet 10/25Gb 2-port SFP28 OCP3 Adapter for HPE | MT_0000000551 |

Mellanox Firmware Package (FWPKG) for Mellanox MCX562A-ACAI Ethernet 10/25Gb 2-port SFP28 OCP3 Adapter for HPE
Version: 16.35.3502 (**Recommended**)
Filename: 16_35_3502-MCX562A-ACA_Ax_Bx.pldm.fwpkg

Important Note!

Disclaimer: Certain software including drivers and documents may be available from NVIDIA. If you select a URL that directs you to <http://www.nvidia.com/>, you are then leaving HPE.com. Please follow the instructions on <http://www.nvidia.com/> to download NVIDIA software or documentation. When downloading the NVIDIA software or documentation, you may be subject to NVIDIA terms and conditions, including licensing terms, if any, provided on its website or otherwise. HPE is not responsible for your use of any software or documents that you download from <http://www.nvidia.com/>, except that HPE may provide a limited warranty for NVIDIA software in accordance with the terms and conditions of your purchase of the HPE product or solution.

A list of known issues with this release is available at: <https://docs.nvidia.com/networking/display/connectx5firmwarev16353502/its/known+issues>

Prerequisites

FWPKG will work only if the firmware version flashed on the adapter is 16.27.1016 or later and iLO5 firmware version must be 2.30 or higher.

Fixes

No fixes are included in version 16.35.3502.

Enhancements

Important : Security Hardening Enhancements - This release contains important reliability improvements and security hardening enhancements. HPE recommends upgrading your device firmware to this version to improve the firmware security and reliability of your device.

New features and changes included in version 16.35.3502:

- Modified the TCP IPv4 flows so that the steering TIR rx_hash_symmetric field is now valid only when both the SRC and DST fields are not set to zero.

Supported Devices and Features

| HPE Part Number | Mellanox Ethernet Only Adapters | PSID |
|------------------------|--|---------------|
| P10112-B21 | Mellanox MCX562A-ACAI Ethernet 10/25Gb 2-port SFP28 OCP3 Adapter for HPE | MT_0000000241 |

Mellanox Firmware Package (FWPKG) for HPE Ethernet 100Gb 1-port QSFP28 PCIe3 x16 MCX515A-CCAT Adapter : HPE part numbers P31246-B21 and P31246-H21

Version: 16.35.4030 (**Recommended**)

Filename: 16_35_4030-MCX515A-CCA_HPE_Ax.pldm.fwpkg

Important Note!

For PLDM enabled VPI (Virtual Protocol Interconnect) adapters supporting both InfiniBand mode and Ethernet modes, every firmware version is made available in two different formats at HPE.com:

1. HPE signed PLDM Firmware Package (.FWPKG filename extension) updatable via iLO.
2. Firmware binary (.bin filename extension) updatable via mstflint utility from the Operating System.

Choose the appropriate firmware file format based on your preference and what suits your environment.

Disclaimer: Certain software including drivers and documents may be available from NVIDIA. If you select a URL that directs you to <http://www.nvidia.com/>, you are then leaving HPE.com. Please follow the instructions on <http://www.nvidia.com/> to download NVIDIA software or documentation. When downloading the NVIDIA software or documentation, you may be subject to NVIDIA terms and conditions, including licensing terms, if any, provided on its website or otherwise. HPE is not responsible for your use of any software or documents that you download from <http://www.nvidia.com/>, except that HPE may provide a limited warranty for NVIDIA software in accordance with the terms and conditions of your purchase of the HPE product or solution.

A list of known issues with this release is available at: <https://docs.nvidia.com/networking/display/connectx5firmwarev16354030/its/known+issues>

Prerequisites

FWPKG will work only if the firmware version flashed on the adapter is 16.27.1016 or later and iLO5 firmware version must be 2.30 or higher.

Fixes

The following issues have been fixed in version 16.35.4030:

- VF FLR would get stuck when its PF triggered the FLR as well.
- Unexpected source UDP port appeared in RoCE packets when the firmware ignored a non-PF driver configuration for RoCE source UDP port control (as set in SET_HCA_CAP.sw_r_roce_src_udp_port).

Enhancements

Important : Security Hardening Enhancements - This release contains important reliability improvements and security hardening enhancements. HPE recommends upgrading your device firmware to this version to improve the firmware security and reliability of your device.

New features and changes included in version 16.35.4030:

- Added support for postponing QP timeout "retry exceeded" errors for traffic directed at specific destinations. This new capability prevents broken connections for destinations in downtime because of live migration.

Supported Devices and Features

This software package contains the following firmware versions:

| Mellanox Ethernet Only Adapters | Firmware Version | PSID |
|--|-------------------------|---------------|
| HPE Ethernet 100Gb 1-port QSFP28 PCIe3 x16 MCX515A-CCAT Adapter(P31246-B21 and P31246-H21) | 16.35.4030 | MT_0000000591 |

Mellanox Firmware Package (FWPKG) for HPE InfiniBand HDR/Ethernet 200Gb 1-port QSFP56 PCIe4 x16 MCX653105A-HDAT Adapter : HPE part numbers P23664-B21 and P23664-H21

Version: 20.41.1000 **(Recommended)**

Filename: 20_41_1000-MCX653105A-HDA_HPE_Ax.pldm.fwpkg

Important Note!

For PLDM enabled VPI (Virtual Protocol Interconnect) adapters supporting both InfiniBand mode and Ethernet modes, every firmware version is made available in two different formats at HPE.com:

1. HPE signed PLDM Firmware Package (.FWPKG filename extension) updatable via iLO.
2. Firmware binary (.bin filename extension) updatable via mstflint utility from the Operating System.

Choose the appropriate firmware file format based on your preference and what suits your environment.

Disclaimer: Certain software including drivers and documents may be available from NVIDIA. If you select a URL that directs you to <http://www.nvidia.com/>, you are then leaving HPE.com. Please follow the instructions on <http://www.nvidia.com/> to download NVIDIA software or documentation. When downloading the NVIDIA software or documentation, you may be subject to NVIDIA terms and conditions, including licensing terms, if any, provided on its website or otherwise. HPE is not responsible for your use of any software or documents that you download from <http://www.nvidia.com/>, except that HPE may provide a limited warranty for NVIDIA software in accordance with the terms and conditions of your purchase of the HPE product or solution.

A list of known issues with this release is available

at: <https://docs.nvidia.com/networking/display/connectx6firmwarev20411000/known+issues>

Prerequisites

FWPKG will work only if the firmware version flashed on the adapter is 20.27.1016 or later and iLO5 firmware version must be 2.30 or higher.

Fixes

No fixes are included in version 20.41.1000.

Enhancements

Security Hardening Enhancements: This release contains important reliability improvements and security hardening enhancements. HPE recommends upgrading your device's firmware to this release to improve the firmware security and reliability of your device.

New features and changes included in version 20.41.1000:

- Added support for steering match on packet I4_type through FTG/FTE.

Supported Devices and Features

This software package contains the following firmware versions:

| Mellanox InfiniBand Adapter | Firmware Version | PSID |
|---|-------------------------|---------------|
| HPE InfiniBand HDR/Ethernet 200Gb 1-port QSFP56 PCIe4 x16 MCX653105A-HDAT Adapter (P23664-B21 and P23664-H21) | 20.41.1000 | MT_0000000451 |

Mellanox Firmware Package (FWPKG) for HPE InfiniBand HDR/Ethernet 200Gb 1-port QSFP56 PCIe4 x16 OCP3 MCX653435A-HDAI Adapter : HPE part numbers P31323-B21 and P31323-H21

Version: 20.41.1000 (**Recommended**)

Filename: 20_41_1000-MCX653435A-HDA_HPE_Ax.pldm.fwpkg

Important Note!

For PLDM enabled VPI (Virtual Protocol Interconnect) adapters supporting both InfiniBand mode and Ethernet modes, every firmware version is made available in two different formats at HPE.com:

1. HPE signed PLDM Firmware Package (.FWPKG filename extension) updatable via iLO.
2. Firmware binary (.bin filename extension) updatable via mstflint utility from the Operating System.

Choose the appropriate firmware file format based on your preference and what suits your environment.

Disclaimer: Certain software including drivers and documents may be available from NVIDIA. If you select a URL that directs you to <http://www.nvidia.com/>, you are then leaving HPE.com. Please follow the instructions on <http://www.nvidia.com/> to download NVIDIA software or documentation. When downloading the NVIDIA software or documentation, you may be subject to NVIDIA terms and conditions, including licensing terms, if any, provided on its website or otherwise. HPE is not responsible for your use of any software or documents that you download from <http://www.nvidia.com/>, except that HPE may provide a limited warranty for NVIDIA software in accordance with the terms and conditions of your purchase of the HPE product or solution.

A list of known issues with this release is available

at: <https://docs.nvidia.com/networking/display/connectx6firmwarev20411000/known+issues>

Prerequisites

FWPKG will work only if the firmware version flashed on the adapter is 20.27.1016 or later and iLO5 firmware version must be 2.30 or higher.

Fixes

No fixes are included in version 20.41.1000.

Enhancements

Security Hardening Enhancements: This release contains important reliability improvements and security hardening enhancements. HPE recommends upgrading your device's firmware to this release to improve the firmware security and reliability of your device.

New features and changes included in version 20.41.1000:

- Added support for steering match on packet I4_type through FTG/FTE.

Supported Devices and Features

This software package contains the following firmware versions:

| Mellanox InfiniBand Adapter | Firmware Version | PSID |
|--|------------------|---------------|
| HPE InfiniBand HDR/Ethernet 200Gb 1-port QSFP56 PCIe4 x16 OCP3 MCX653435A-HDAI Adapter (P31323-B21 and P31323-H21) | 20.41.1000 | MT_0000000592 |

Mellanox Firmware Package (FWPKG) for HPE InfiniBand HDR/Ethernet 200Gb 2-port QSFP56 PCIe4 x16 MCX653106A-HDAT Adapter : HPE part numbers P31324-B21 and P31324-H21

Version: 20.41.1000 (**Recommended**)

Filename: 20_41_1000-MCX653106A-HDA_HPE_Ax.pldm.fwpkg

Important Note!

For PLDM enabled VPI (Virtual Protocol Interconnect) adapters supporting both InfiniBand mode and Ethernet modes, every firmware version is made available in two different formats at HPE.com:

1. HPE signed PLDM Firmware Package (.FWPKG filename extension) updatable via iLO.
2. Firmware binary (.bin filename extension) updatable via mstflint utility from the Operating System.

Choose the appropriate firmware file format based on your preference and what suits your environment.

ConnectX-6 VPI supports having one port as InfiniBand and the other port as Ethernet according to the following matrix of combinations.

| Port #2 - InfiniBand | | | | |
|----------------------|------------|---------------|---------------|-----------|
| Port #1 - Ethernet | HDR/HDR100 | EDR | FDR | QDR |
| 200GbE/50GbE | supported | not supported | not supported | supported |
| 100GbE/25GbE | supported | not supported | not supported | supported |
| 40GbE/10GbE | supported | not supported | not supported | supported |
| 1GbE | supported | not supported | not supported | supported |

| Port #2 - Ethernet | | | | |
|----------------------|---------------|---------------|---------------|---------------|
| Port #1 - InfiniBand | 200GbE/50GbE | 100GbE/25GbE | 40GbE/10GbE | 1GbE |
| HDR / HDR100 | supported | supported | not supported | supported |
| EDR | supported | supported | not supported | supported |
| FDR | not supported | not supported | not supported | not supported |
| QDR/SDR | supported | supported | not supported | supported |

Disclaimer: Certain software including drivers and documents may be available from NVIDIA. If you select a URL that directs you to <http://www.nvidia.com/>, you are then leaving HPE.com. Please follow the instructions on <http://www.nvidia.com/> to download NVIDIA software or documentation. When downloading the NVIDIA software or documentation, you may be subject to NVIDIA terms and conditions, including licensing terms, if any, provided on its website or otherwise. HPE is not responsible for your use of any software or documents that you download from <http://www.nvidia.com/>, except that HPE may provide a limited warranty for NVIDIA software in accordance with the terms and conditions of your purchase of the HPE product or solution.

A list of known issues with this release is available

at: <https://docs.nvidia.com/networking/display/connectx6firmwarev20411000/known+issues>

Prerequisites

FWPKG will work only if the firmware version flashed on the adapter is 20.27.1016 or later and iLO5 firmware version must be 2.30 or higher.

Fixes

No fixes are included in version 20.41.1000.

Enhancements

Security Hardening Enhancements: This release contains important reliability improvements and security hardening enhancements. HPE recommends upgrading your device's firmware to this release to improve the firmware security and reliability of your device.

New features and changes included in version 20.41.1000:

- o Added support for steering match on packet I4_type through FTG/FTE.

Supported Devices and Features

This software package contains the following firmware versions:

| Mellanox InfiniBand Adapter | Firmware Version | PSID |
|--|-------------------------|---------------|
| HPE InfiniBand HDR/Ethernet 200Gb 2-port QSFP56 PCIe4 x16 MCX653106A-HDAT Adapter(P31324-B21 and P31324-H21) | 20.41.1000 | MT_0000000594 |

Mellanox Firmware Package (FWPKG) for HPE InfiniBand HDR/Ethernet 200Gb 2-port QSFP56 PCIe4 x16 OCP3 MCX653436A-HDAI Adapter : HPE part numbers P31348-B21 and P31348-H21

Version: 20.41.1000 (**Recommended**)

Filename: 20_41_1000-MCX653436A-HDA_HPE_Ax.pldm.fwpkg

Important Note!

For PLDM enabled VPI (Virtual Protocol Interconnect) adapters supporting both InfiniBand mode and Ethernet modes, every firmware version is made available in two different formats at HPE.com:

1. HPE signed PLDM Firmware Package (.FWPKG filename extension) updatable via iLO.
2. Firmware binary (.bin filename extension) updatable via mstflint utility from the Operating System.

Choose the appropriate firmware file format based on your preference and what suits your environment.

ConnectX-6 VPI supports having one port as InfiniBand and the other port as Ethernet according to the following matrix of combinations.

| Port #2 - InfiniBand | | | | |
|-----------------------------|-------------------|---------------|---------------|------------|
| Port #1 - Ethernet | HDR/HDR100 | EDR | FDR | QDR |
| 200GbE/50GbE | supported | not supported | not supported | supported |
| 100GbE/25GbE | supported | not supported | not supported | supported |
| 40GbE/10GbE | supported | not supported | not supported | supported |
| 1GbE | supported | not supported | not supported | supported |

| Port #2 - Ethernet | | | | |
|-----------------------------|---------------------|---------------------|--------------------|---------------|
| Port #1 - InfiniBand | 200GbE/50GbE | 100GbE/25GbE | 40GbE/10GbE | 1GbE |
| HDR / HDR100 | supported | supported | not supported | supported |
| EDR | supported | supported | not supported | supported |
| FDR | not supported | not supported | not supported | not supported |
| QDR/SDR | supported | supported | not supported | supported |

Disclaimer: Certain software including drivers and documents may be available from NVIDIA. If you select a URL that directs you to <http://www.nvidia.com/>, you are then leaving HPE.com. Please follow the instructions on <http://www.nvidia.com/> to download NVIDIA software or documentation. When downloading the NVIDIA software or documentation, you may be subject to NVIDIA terms and conditions, including licensing terms, if any, provided on its website or otherwise. HPE is not responsible for your use of any software or documents that you download from <http://www.nvidia.com/>, except that HPE may provide a limited warranty for NVIDIA software in accordance with the terms and conditions of your purchase of the HPE product or solution.

A list of known issues with this release is available at: <https://docs.nvidia.com/networking/display/connectx6firmwarev20411000/known+issues>

Prerequisites

FWPKG will work only if the firmware version flashed on the adapter is 20.27.1016 or later and iLO5 firmware version must be 2.30 or higher.

Fixes

No fixes are included in version 20.41.1000.

Enhancements

Security Hardening Enhancements: This release contains important reliability improvements and security hardening enhancements. HPE recommends upgrading your device's firmware to this release to improve the firmware security and reliability of your device.

New features and changes included in version 20.41.1000:

- Added support for steering match on packet I4_type through FTG/FTE.

Supported Devices and Features

This software package contains the following firmware versions:

| Mellanox InfiniBand Adapter | Firmware Version | PSID |
|--|-------------------------|---------------|
| HPE InfiniBand HDR/Ethernet 200Gb 2-port QSFP56 PCIe4 x16 OCP3 MCX653436A-HDAI Adapter (P31348-B21 and P31348-H21) | 20.41.1000 | MT_0000000593 |

Mellanox Firmware Package (FWPKG) for HPE InfiniBand HDR100/Ethernet 100Gb 1-port QSFP56 PCIe4 x16 MCX653105A-ECAT Adapter : HPE part numbers P23665-B21 and P23665-H21

Version: 20.41.1000 **(Recommended)**

Filename: 20_41_1000-MCX653105A-ECA_HPE_Ax.pldm.fwpgk

Important Note!

For PLDM enabled VPI (Virtual Protocol Interconnect) adapters supporting both InfiniBand mode and Ethernet modes, every firmware version is made available in two different formats at HPE.com:

1. HPE signed PLDM Firmware Package (.FWPKG filename extension) updatable via iLO.
2. Firmware binary (.bin filename extension) updatable via mstflint utility from the Operating System.

Choose the appropriate firmware file format based on your preference and what suits your environment.

Disclaimer: Certain software including drivers and documents may be available from NVIDIA. If you select a URL that directs you to <http://www.nvidia.com/>, you are then leaving HPE.com. Please follow the instructions on <http://www.nvidia.com/> to download NVIDIA software or documentation. When downloading the NVIDIA software or documentation, you may be subject to NVIDIA terms and conditions, including licensing terms, if any, provided on its website or otherwise. HPE is not responsible for your use of any software or documents that you download from <http://www.nvidia.com/>, except that HPE may provide a limited warranty for NVIDIA software in accordance with the terms and conditions of your purchase of the HPE product or solution.

A list of known issues with this release is available at: <https://docs.nvidia.com/networking/display/connectx6firmwarev20411000/known+issues>

Prerequisites

FWPKG will work only if the firmware version flashed on the adapter is 20.27.1016 or later and iLO5 firmware version must be 2.30 or higher.

Fixes

No fixes are included in version 20.41.1000.

Enhancements

Security Hardening Enhancements: This release contains important reliability improvements and security hardening enhancements. HPE recommends upgrading your device's firmware to this release to improve the firmware security and reliability of your device.

New features and changes included in version 20.41.1000:

- Added support for steering match on packet I4_type through FTG/FTE.

Supported Devices and Features

This software package contains the following firmware versions:

| Mellanox InfiniBand Adapter | Firmware Version | PSID |
|--|------------------|---------------|
| HPE InfiniBand HDR100/Ethernet 100Gb 1-port QSFP56 PCIe4 x16 MCX653105A-ECAT Adapter (P23665-B21 and P23665-H21) | 20.41.1000 | MT_0000000452 |

Mellanox Firmware Package (FWPKG) for HPE InfiniBand HDR100/Ethernet 100Gb 2-port QSFP56 PCIe4 x16 MCX653106A-ECAT Adapter :
HPE part numbers P23666-B21 and P23666-H21
Version: 20.41.1000 (**Recommended**)
Filename: 20_41_1000-MCX653106A-ECA_HPE_Ax.pldm.fwpgk

Important Note!

For PLDM enabled VPI (Virtual Protocol Interconnect) adapters supporting both InfiniBand mode and Ethernet modes, every firmware version is made available in two different formats at HPE.com:

1. HPE signed PLDM Firmware Package (.FWPKG filename extension) updatable via iLO.
2. Firmware binary (.bin filename extension) updatable via mstflint utility from the Operating System.

Choose the appropriate firmware file format based on your preference and what suits your environment.

ConnectX-6 VPI supports having one port as InfiniBand and the other port as Ethernet according to the following matrix of combinations.

| Port #2 - InfiniBand | | | | |
|----------------------|------------|---------------|---------------|-----------|
| Port #1 - Ethernet | HDR/HDR100 | EDR | FDR | QDR |
| 50GbE | supported | not supported | not supported | supported |
| 100GbE/25GbE | supported | not supported | not supported | supported |
| 40GbE/10GbE | supported | not supported | not supported | supported |
| 1GbE | supported | not supported | not supported | supported |

| Port #2 - Ethernet | | | | |
|----------------------|-----------|--------------|---------------|-----------|
| Port #1 - InfiniBand | 50GbE | 100GbE/25GbE | 40GbE/10GbE | 1GbE |
| HDR / HDR100 | supported | supported | not supported | supported |
| EDR | supported | supported | not supported | supported |

| | | | | |
|----------------|---------------|---------------|---------------|---------------|
| FDR | not supported | not supported | not supported | not supported |
| QDR/SDR | supported | supported | not supported | supported |

Disclaimer: Certain software including drivers and documents may be available from NVIDIA. If you select a URL that directs you to <http://www.nvidia.com/>, you are then leaving HPE.com. Please follow the instructions on <http://www.nvidia.com/> to download NVIDIA software or documentation. When downloading the NVIDIA software or documentation, you may be subject to NVIDIA terms and conditions, including licensing terms, if any, provided on its website or otherwise. HPE is not responsible for your use of any software or documents that you download from <http://www.nvidia.com/>, except that HPE may provide a limited warranty for NVIDIA software in accordance with the terms and conditions of your purchase of the HPE product or solution.

A list of known issues with this release is available at: <https://docs.nvidia.com/networking/display/connectx6firmwarev20411000/known+issues>

Prerequisites

FWPKG will work only if the firmware version flashed on the adapter is 20.27.1016 or later and iLO5 firmware version must be 2.30 or higher.

Fixes

No fixes are included in version 20.41.1000.

Enhancements

Security Hardening Enhancements: This release contains important reliability improvements and security hardening enhancements. HPE recommends upgrading your device's firmware to this release to improve the firmware security and reliability of your device.

New features and changes included in version 20.41.1000:

- Added support for steering match on packet I4_type through FTG/FTE.

Supported Devices and Features

This software package contains the following firmware versions:

| Mellanox InfiniBand Adapter | Firmware Version | PSID |
|--|-------------------------|---------------|
| HPE InfiniBand HDR100/Ethernet 100Gb 2-port QSFP56 PCIe4 x16 MCX653106A-ECAT Adapter (P23666-B21 and P23666-H21) | 20.41.1000 | MT_0000000453 |

Mellanox Firmware Package (FWPKG) for Mellanox MCX623105AS-VDAT Ethernet 200Gb 1-port QSFP56 Adapter for HPE

Version: 22.41.1000 **(Recommended)**

Filename: 22_41_1000-MCX623105AS-VDA_Ax.pldm.fwpkg

Important Note!

Disclaimer: Certain software including drivers and documents may be available from NVIDIA. If you select a URL that directs you to <http://www.nvidia.com/>, you are then leaving HPE.com. Please follow the instructions on <http://www.nvidia.com/> to download NVIDIA software or documentation. When downloading the NVIDIA software or documentation, you may be subject to NVIDIA terms and conditions, including licensing terms, if any, provided on its website or otherwise. HPE is not responsible for your use of any software or documents that you download from <http://www.nvidia.com/>, except that HPE may provide a limited warranty for NVIDIA software in accordance with the terms and conditions of your purchase of the HPE product or solution.

A list of known issues with this release is available at: <https://docs.nvidia.com/networking/display/connectx6dxfirmwarev22411000/known+issues>

Prerequisites

FWPKG will work only if the firmware version flashed on the adapter is 22.27.1016 or later and iLO5 firmware version must be 2.30 or higher.

Fixes

The following issues have been fixed in version 22.41.1000:

- GTP length field was automatically modified at the TX side when an incorrect or invalid length was detected.
- Switch port would go down due to MC packets mirrored back to the switch when in promiscuous mode.
- Traffic failure occurred when modifying the VIRTIO_NET_F_MRG_RXBUF bit for the VDPA device during traffic.
- The second mkey index returned even if it was not set in the creation of the virtio q when querying virtio q object.
- Traffic loss occurred after performing Live Migration with virtio vq "frozen-ready" feature.

Note: When the traffic load is high, and the vq frozen-ready cap is on, traffic loss might still be experienced after modifying the vq from suspend to ready mode.

Enhancements

Security Hardening Enhancements: This release contains important reliability improvements and security hardening enhancements. HPE recommends upgrading your device's firmware to this release to improve the firmware security and reliability of your device.

New features and changes included in version 22.41.1000:

- The new unified_fdb subdomain simplifies the FDB model by eliminating the need to duplicate rules for RX and TX tables. This domain is directionless, meaning no RX/TX specific actions are allowed. Firmware now handles packet transitions IN and OUT of the unified domain, allowing for a more streamlined packet flow management. Software can now transition between unified_fdb and FDB_RX/FDB_TX domains as long as the packet maintains the same direction, without the risk of dropping the packet when crossing between RX and TX.
- Implemented Deterministic Random Bit Generator (DRBG) algorithm on top of firmware TRNG (the source for raw data input) in accordance with NIST SP800-90A.
- Added support for vDPA virtual queue state change from suspend to ready, and discrete mkey for descriptor. vDPA Live Migration uses these two new capabilities to reduce downtime since vq can go back to ready state for traffic and descriptor-only-mkey can help reduce mkey mapping time.
- Added the ability to generate up to 2^30 STE objects through the general object creation command.
- Added a new NVConfig option to copy AR bit from the BTH header to the DHCP header.
- Added the option to provide field's offset and length in Steering add_action option.
- Added support for steering match on packet I4_type through FTG/FTE.
- Extended Flex Parser merge mechanism to support hardware capabilities.
- Enabled the option to disable the native parser when the parse graph node is configured with the same conditions.
- Added support for father/son headers parsing.
- Added support for tunnel_offload in LRO.

Supported Devices and Features

| HPE Part Number | Mellanox Ethernet Only Adapters | PSID |
|------------------------|--|---------------|
| P10180-B21 | Mellanox MCX623105AS-VDAT Ethernet 200Gb 1-port QSFP56 Adapter for HPE | MT_0000000435 |

Mellanox Firmware Package (FWPKG) for Mellanox MCX623106AS-CDAT Ethernet 100Gb 2-port QSFP56 Adapter for HPE
Version: 22.41.1000 (**Recommended**)
Filename: 22_41_1000-MCX623106AS-CDA_Ax.pldm.fwpkg

Important Note!

Disclaimer: Certain software including drivers and documents may be available from NVIDIA. If you select a URL that directs you to <http://www.nvidia.com/>, you are then leaving HPE.com. Please follow the instructions on <http://www.nvidia.com/> to download NVIDIA software or documentation. When downloading the NVIDIA software or documentation, you may be subject to NVIDIA terms and conditions, including licensing terms, if any, provided on its website or otherwise. HPE is not responsible for your use of any software or documents that you download from <http://www.nvidia.com/>, except that HPE may provide a limited warranty for NVIDIA software in accordance with the terms and conditions of your purchase of the HPE product or solution.

A list of known issues with this release is available

at: <https://docs.nvidia.com/networking/display/connectx6dxfirmwarev22411000/known+issues>

Prerequisites

FWPKG will work only if the firmware version flashed on the adapter is 22.27.1016 or later and iLO5 firmware version must be 2.30 or higher.

Fixes

The following issues have been fixed in version 22.41.1000:

- o GTP length field was automatically modified at the TX side when an incorrect or invalid length was detected.
- o Switch port would go down due to MC packets mirrored back to the switch when in promiscuous mode.
- o Traffic failure occurred when modifying the VIRTIO_NET_F_MRG_RXBUF bit for the VDPA device during traffic.
- o The second mkey index returned even if it was not set in the creation of the virtio q when querying virtio q object.
- o Traffic loss occurred after performing Live Migration with virtio vq "frozen-ready" feature.

Note: When the traffic load is high, and the vq frozen-ready cap is on, traffic loss might still be experienced after modifying the vq from suspend to ready mode.

Enhancements

Security Hardening Enhancements: This release contains important reliability improvements and security hardening enhancements. HPE recommends upgrading your device's firmware to this release to improve the firmware security and reliability of your device.

New features and changes included in version 22.41.1000:

- o The new unified_fdb subdomain simplifies the FDB model by eliminating the need to duplicate rules for RX and TX tables. This domain is directionless, meaning no RX/TX specific actions are allowed. Firmware now handles packet transitions IN and OUT of the unified domain, allowing for a more streamlined packet flow management. Software can now transition between unified_fdb and FDB_RX/FDB_TX domains as long as the packet maintains the same direction, without the risk of dropping the packet when crossing between RX and TX.
- o Implemented Deterministic Random Bit Generator (DRBG) algorithm on top of firmware TRNG (the source for raw data input) in accordance with NIST SP800-90A.
- o Added support for vDPA virtual queue state change from suspend to ready, and discrete mkey for descriptor. vDPA Live Migration uses these two new capabilities to reduce downtime since vq can go back to ready state for traffic and descriptor-only-mkey can help reduce mkey mapping time.
- o Added the ability to generate up to 2^{30} STE objects through the general object creation command.
- o Added a new NVConfig option to copy AR bit from the BTH header to the DHCP header.
- o Added the option to provide field's offset and length in Steering add_action option.
- o Added support for steering match on packet I4_type through FTG/FTE.
- o Extended Flex Parser merge mechanism to support hardware capabilities.
- o Enabled the option to disable the native parser when the parse graph node is configured with the same conditions.
- o Added support for father/son headers parsing.
- o Added support for tunnel_offload in LRO.

Supported Devices and Features

| HPE Part Number | Mellanox Ethernet Only Adapters | PSID |
|-----------------|--|---------------|
| P25960-B21 | Mellanox MCX623106AS-CDAT Ethernet 100Gb 2-port QSFP56 Adapter for HPE | MT_0000000437 |

Mellanox Firmware Package(FWPKG) for HPE Ethernet 10/25Gb 2-port SFP28 MCX512F-ACHT Adapter
Version: 16.35.3502 (**Recommended**)
Filename: 16_35_3502-MCX512F-ACH_Ax_Bx.pldm.fwpkg

Important Note!

Disclaimer: Certain software including drivers and documents may be available from NVIDIA. If you select a URL that directs you to <https://www.nvidia.com/>, you are then leaving HPE.com. Please follow the instructions on <https://www.nvidia.com/> to download NVIDIA software or documentation. When downloading the NVIDIA software or documentation, you may be subject to NVIDIA terms and conditions, including licensing terms, if any, provided on its website or otherwise. HPE is not responsible for your use of any software or documents that you download from <https://www.nvidia.com/>, except that HPE may provide a limited warranty for NVIDIA software in accordance with the terms and conditions of your purchase of the HPE product or solution.

A list of known issues with this release is available at: <https://docs.nvidia.com/networking/display/connectx5firmwarev16353502lts/known+issues>

Prerequisites

FWPKG will work only if the firmware version flashed on the adapter is 16.27.1016 or later and iLO5 firmware version must be 2.30 or higher.

Fixes

No fixes are included in version 16.35.3502.

Enhancements

Important : Security Hardening Enhancements - This release contains important reliability improvements and security hardening enhancements. HPE recommends upgrading your device firmware to this version to improve the firmware security and reliability of your device.

New features and changes included in version 16.35.3502:

- Modified the TCP IPv4 flows so that the steering TIR rx_hash_symmetric field is now valid only when both the SRC and DST fields are not set to zero.

Supported Devices and Features

| HPE Part Number | Mellanox Ethernet Only Adapters | PSID |
|------------------------|--|---------------|
| P13188-B21 | HPE Ethernet 10/25Gb 2-port SFP28 MCX512F-ACHT Adapter | MT_0000000416 |

Online Firmware Upgrade Utility (ESXi 8.0) for HPE Ethernet 10Gb 2-port 548SFP+ Adapter
Version: 1.0.0 (**Recommended**)
Filename: CP053859.compsig; CP053859.zip

Prerequisites

Use iLO5 firmware version 2.30 or higher with ConnectX4-Lx firmware version 14.32.1010. Thermal sensor reporting on the adapter will not be functional with older versions of iLO5 firmware.

Fixes

The following issues have been fixed in version 14.32.1010:

- Firmware got into an unresponsive state and caused unexpected behavior when connecting an optical transceiver that support RxLOS and the remote side port was down.
- The system could not create more than 128K QPs.
- On rare occasions, the system got into an unresponsive state when a peer port went down while using an Optical module.
- Packet Pacing rate was used if asymmetric VFs was enabled.
- Incorrect RNR timeout when trying to set it during the rts2rts_qp transition.
- Issue with RSS on IPSec flows in ConnectX-4 Lx led to performance degradation. In this scenario, the SPI optimization caused packets from a given host to hash to the same CPU core. The fix was to ignore SPI optimization according to l4_type in ConnectX-4 Lx adapter cards.
- The GetInventory NC-SI command reported leading 0xf in firmware version when it started with 0.

Enhancements

Firmware for the following device has been updated to 14.32.1010:

- P11338-B21 (HPE Ethernet 10Gb 2-port 548SFP+ Adapter)

New features and changes included in version 14.32.1010:

- Added 3 new assert filters (Health buffer, NVlog, FW trace). The assert will be exposed now if its severity level is equal to or above the new filter.
- Enabled Rate Limit per VM instead of VM-TC. This capability is implemented by adding support to a new Scheduling element type: rate limit elements that will connect to the rate_limit and will share its rate limit.
- Added support for asymmetrical VFs per PF. To enable it:PF_NUM_OF_VF_VALID must be true, and PF_NUM_OF_VF to a non-zero value.
- Limited the external loopback speed to the used module's capabilities.

- Improved linkup time when using the fast linkup capability.
- Added support for the slow_restart and slow_restart_idle parameters to enable Zero Touch RoCE capability.

Supported Devices and Features

| HPE Part Number | Mellanox Ethernet Only Adapters | PSID |
|------------------------|--|---------------|
| P11338-B21 | HPE Ethernet 10Gb 2-port 548SFP+ Adapter | HPE0000000038 |

Online Firmware Upgrade Utility (ESXi 8.0) for HPE Mellanox Ethernet only adapters

Version: 1.0.4 (**Recommended**)

Filename: CP061398.compsig; CP061398.zip

Important Note!

The Firmware Upgrade Utility has been split into 2 packages for Mellanox Ethernet Only NIC adapters, one supporting Synergy platforms and the other supporting ProLiant and Apollo platforms. This package supports Mellanox Ethernet Only NIC adapters on ProLiant and Apollo servers.

Prerequisites

Use iLO5 firmware version 2.30 or higher with ConnectX4-Lx/ConnectX5 firmware version 14.32.1010/16.32.1010 (or later) respectively. Thermal sensor reporting on the adapter will not be functional with older versions of iLO5 firmware.

Fixes

The following issues have been fixed in firmware version 14.32.1010:

- Firmware got into an unresponsive state and caused unexpected behavior when connecting an optical transceiver that support RxLOS and the remote side port was down.
- The system could not create more than 128K QPs.
- On rare occasions, the system got into an unresponsive state when a peer port went down while using an Optical module.
- Packet Pacing rate was used if asymmetric VFs was enabled.
- Incorrect RNR timeout when trying to set it during the rts2rts_qp transition.
- Issue with RSS on IPSec flows in ConnectX-4 Lx led to performance degradation. In this scenario, the SPI optimization caused packets from a given host to hash to the same CPU core. The fix was to ignore SPI optimization according to l4_type in ConnectX-4 Lx adapter cards.
- The GetInventory NC-SI command reported leading 0xf in firmware version when it started with 0.

No fixes are included in firmware version 16.35.3502.

Enhancements

Firmware for the following devices has been updated to 14.32.1010:

- 817749-B21 (HPE Ethernet 25Gb 2-port 640FLR-SFP28 Adapter)
- 817753-B21 (HPE Ethernet 25Gb 2-port 640SFP28 Adapter)

Firmware for the following device has been updated to 16.35.3502:

- 874253-B21 (HPE Ethernet 100Gb 1-port 842QSFP28 Adapter)

New features and changes included in firmware version 14.32.1010:

- Added 3 new assert filters (Health buffer, NVlog, FW trace). The assert will be exposed now if its severity level is equal to or above the new filter.
- Enabled Rate Limit per VM instead of VM-TC. This capability is implemented by adding support to a new Scheduling element type: rate limit elements that will connect to the rate_limit and will share its rate limit.
- Added support for asymmetrical VFs per PF. To enable it: PF_NUM_OF_VF_VALID must be true, and PF_NUM_OF_VF to a non-zero value.
- Limited the external loopback speed to the used module's capabilities.
- Improved linkup time when using the fast linkup capability.
- Added support for the slow_restart and slow_restart_idle parameters to enable Zero Touch RoCE capability.

New features and changes included in firmware version 16.35.3502:

- Modified the TCP IPv4 flows so that the steering TIR rx_hash_symmetric field is now valid only when both the SRC and DST fields are not set to zero.

Supported Devices and Features

| HPE Part Number | Mellanox Ethernet Only Adapters | PSID |
|-----------------|---|---------------|
| 817749-B21 | HPE Ethernet 25Gb 2-port 640FLR-SFP28 Adapter | HP_2690110034 |
| 817753-B21 | HPE Ethernet 25Gb 2-port 640SFP28 Adapter | HP_2420110034 |
| 874253-B21 | HPE Ethernet 100Gb 1-port 842QSFP28 Adapter | HPE0000000014 |

Online Firmware Upgrade Utility (ESXi 8.0) for Mellanox Open Ethernet cards

Version: 1.0.4 **(Recommended)**

Filename: CP061402.compsig; CP061402.zip

Important Note!

On Adapter Firmware rewrite scenario, SUM will always discover the Mellanox Open adapter firmware smart component as applicable and select it for deployment. If the server iLO5 firmware version is older than 2.30.

Prerequisites

Use iLO5 firmware version 2.30 or higher with ConnectX4-Lx/ConnectX5 firmware version 14.32.1010/16.32.1010 respectively. Thermal sensor reporting on the adapter will not be functional with older versions of iLO5 firmware.

Fixes

The following issues have been fixed in firmware version 14.32.1010:

- Firmware got into an unresponsive state and caused unexpected behavior when connecting an optical transceiver that support RxLOS and the remote side port was down.
- The system could not create more than 128K QPs.
- On rare occasions, the system got into an unresponsive state when a peer port went down while using an Optical module.
- Packet Pacing rate was used if asymmetric VFs was enabled.
- Incorrect RNR timeout when trying to set it during the rts2rts_qp transition.
- Issue with RSS on IPsec flows in ConnectX-4 Lx led to performance degradation. In this scenario, the SPI optimization caused packets from a given host to hash to the same CPU core. The fix was to ignore SPI optimization according to l4_type in ConnectX-4 Lx adapter cards.
- The GetInventory NC-SI command reported leading 0xf in firmware version when it started with 0.

No fixes are included in firmware version 16.35.3502.

Enhancements

Firmware for the following devices has been updated to 14.32.1010:

- P21930-B21 (HPE Ethernet 10Gb 2-port SFP+ MCX4121A-XCAT Adapter)
- P11341-B21 (HPE Ethernet 10Gb 2-port SFP+ MCX4621A-ACAB OCP3 Adapter)

Firmware for the following device has been updated to 16.35.3502:

- P21927-B21 (HPE Ethernet 100Gb 2-Port QSFP28 MCX516A-CCHT Adapter)

New features and changes included in firmware version 14.32.1010:

- Added 3 new assert filters (Health buffer, NVlog, FW trace). The assert will be exposed now if its severity level is equal to or above the new filter.
- Enabled Rate Limit per VM instead of VM-TC. This capability is implemented by adding support to a new Scheduling element type: rate limit elements that will connect to the rate_limit and will share its rate limit.
- Added support for asymmetrical VFs per PF. To enable it: PF_NUM_OF_VF_VALID must be true, and PF_NUM_OF_VF to a non-zero value.
- Limited the external loopback speed to the used module's capabilities.
- Improved linkup time when using the fast linkup capability.
- Added support for the slow_restart and slow_restart_idle parameters to enable Zero Touch RoCE capability.

New features and changes included in firmware version 16.35.3502:

- Modified the TCP IPv4 flows so that the steering TIR rx_hash_symmetric field is now valid only when both the SRC and DST fields are not set to zero.

Supported Devices and Features

| HPE Part Number | Mellanox Ethernet Only Adapters | PSID |
|-----------------|--|---------------|
| P21930-B21 | HPE Ethernet 10Gb 2-port SFP+ MCX4121A-XCHT Adapter | MT_0000000414 |
| P11341-B21 | HPE Ethernet 10Gb/25Gb 2-port SFP28 MCX4621A-ACAB OCP3 Adapter | MT_0000000238 |
| P21927-B21 | HPE Ethernet 100Gb 2-port QSFP28 MCX516A-CCHT Adapter | MT_0000000417 |

Firmware - Storage Controller

[Top](#)

Controller Firmware Flash for ESXi7.0 and 8.0 - HPE MR216i-a Gen10 Plus Tri Mode Controller

Version: 52.26.3.5487 (**Recommended**)

Filename: CP060618.compsig; CP060618.zip

Fixes

- Fix an issue that PLDM firmware update may fail. The issue may happen on controller, backplane and drive attached to controller.

Controller Firmware Flash for ESXi7.0 and 8.0 - HPE MR216i-p Gen10 Plus Tri Mode Controller

Version: 52.26.3.5487 (**Recommended**)

Filename: CP060617.compsig; CP060617.zip

Fixes

- Fix an issue that PLDM firmware update may fail. The issue may happen on controller, backplane and drive attached to controller.

Controller Firmware Flash for ESXi7.0 and 8.0 - HPE MR416i-a Gen10 Plus Tri Mode Controller

Version: 52.26.3.5487 (**Recommended**)

Filename: CP060616.compsig; CP060616.zip

Fixes

- Fix an issue that PLDM firmware update may fail. The issue may happen on controller, backplane and drive attached to controller.

Controller Firmware Flash for ESXi7.0 and 8.0 - HPE MR416i-p Gen10 Plus Tri Mode Controller

Version: 52.26.3.5487 (**Recommended**)

Filename: CP060615.compsig; CP060615.zip

Fixes

- Fix an issue that PLDM firmware update may fail. The issue may happen on controller, backplane and drive attached to controller.

Firmware Package - HPE Smart Array P408i-p, P408e-p, P408i-a, P408i-c, E208i-p, E208e-p, E208i-c, E208i-a, P204i-c, P416ie-m and P816i-a SR Gen10 and SR308i-o,SR308i-p Gen11 controllers

Version: 7.11 (**Recommended**)

Filename: HPE_SR_Gen10_7.11_A.fwpkg

Fixes

- Fixed an issue where the host experienced BSOD while clearing the controller configuration.
- Fixed controller lockups caused by incorrect address reads and partial RAM initialization for PCIe functions, leading to ECC errors.
- Fixed issues with external storage.
- Fixed issues with the SATA drive.
- Fixed issues with the SED drive.
- Fixed issues with the spare drive.
- Corrected MCTP-related issues.
- Fixed surface scan issues on the RAID 50.
- Fixed issues encountered during heavy I/O operations.
- Fixed volume issues on the failed drive.
- Fixed issues for incorrect Severity reported in Redfish events.
- Fixed issues for incorrect Status reported in Redfish resources.

- Fixed an issue with improper capacity information in Redfish drive Name.
- Fixed an issue where Redfish long running task status is not reported.
- Fixed an issue where DurableNameFormat for RAID volumes are reported as UUID in RDE READ operations, but should be NAA.
- Fixed an issue where failed to take ownership of, or to revert, a SED through Redfish.
- Fixed an issue when a drive hosting a RAID 0 Volume is removed and reinserted, a VolumeOK event is not generated.

Enhancements

- Added support for saving Managed SED master key and reset key in cipher text in controller NVRAM instead of clear text.
- Changed temperature polling period from 1 minute to 5 minutes for HBA mode drives that are in low power state.
- Added support for clearing UREs in unmapped LBA range of fault tolerant logical drives.
- Improved random write and mixed read-write performance.
- Added support for SED encryption configuration through Redfish interface.
- Added support of Redfish Chassis implementation for UBM Backplanes.
- Added Redfish ACTION:
 - Storage.SetEncryptionKey
- Added support for Redfish property PATCH:
 - Storage.EncryptionMode
 - Storage.HotspareActivationPolicy
 - Drive.HostspareReplacementMode
 - Drive.HostspareType
 - Volume.Encrypted
- Added support for Redfish Status.Conditions property to resources:
 - Drive
 - Port
 - StorageController
 - StorageController.CacheSummary
 - Volume
- Added support for Redfish properties:
 - Drive.DriveFormFactor
 - Drive.FirmwareVersion
 - Drive.Manufacture (SAS only)
 - Drive.SlotCapableProtocols
 - StorageController.AssetTag
 - StorageController.Links.PCIeFunction
 - Volume.BlockSizeBytes
 - Volume.LogicalUnitNumber
- Added support for PLDM Type5 UBM PIC firmware flashing behind expander.

Firmware Package - HPE Gen11 Boot Controller NS204i-u, NS204i-d and HPE Gen10 Plus Boot Controller NS204i-p, NS204i-d, NS204i-t, NS204i-r

Version: 1.2.14.1013 **(Recommended)**

Filename: HPE_NS204i_Gen10p_Gen11_1.2.14.1013_A.fwpkg

Important Note!

Current firmware has to be 1.0.14.1063 or later in order to enable PLDM firmware update functionality for the controller. Please find the smart component versions of 1.0.14.1063 in below link:

- Windows: <https://www.hpe.com/global/swpublishing/MTX-be195b2891724ec8bb72c8bb2>
- Linux: <https://www.hpe.com/global/swpublishing/MTX-269e14d0e2524277bf699f433>
- Vmware: <https://www.hpe.com/global/swpublishing/MTX-1ffaca997cf248cd9f832a04c6>

Prerequisites

- iLO 6 version 1.10 or later is required for Gen11 servers.
- iLO 5 version 2.81 or later is required for Gen10/Gen10 Plus servers

Fixes

- Fixed an issue that iLO reports NS204i PLDM firmware update failure, but the firmware update is actually successful and will be activated in next reboot
- Fixed an issue that the M.2 attached are listed in iLO Device Inventory
- Corrected the drive state of performing Storage.ResetToDefaults with ResetAll type
- Allowed empty JSON payload for SecureErase and corrected the returned status when the previous one is either in process or completed.

Enhancements

- Add @Redfish.AllowableValues, @Redfish.AllowablePattern, @Redfish.AllowableNumbers and @Redfish.WritableProperties for Redfish Annotations
 - Add StorageController.Links, Drive.SlotCapableProtocols and Storage.AutoVolumeCreate for Redfish GET
 - Add StorageController.ControllerRates and Volume.DisplayName for Redfish PATCH
-

Firmware Package - HPE MR216i-a Gen10 Plus Tri Mode Controller

Version: 52.26.3-5487 (**Recommended**)

Filename: HPE_MR216i-a_Gen10P_52.26.3-5487_A.fwpkg

Important Note!

- **This firmware version to be used on HPE MR216i-a Gen10 Plus Controller.**

Prerequisites

iLO5 version should be at least 2.98 is required for **chassis&Fabric support**.

Fixes

- Fix an issue that PLDM firmware update may fail. The issue may happen on controller, backplane and drive attached to controller.
-

Firmware Package - HPE MR216i-p Gen10 Plus Tri Mode Controller

Version: 52.26.3-5487 (**Recommended**)

Filename: HPE_MR216i-p_Gen10P_52.26.3-5487_A.fwpkg

Important Note!

- **This firmware version to be used on HPE MR216i-p Gen10 Plus Controller.**

Prerequisites

iLO5 version should be at least 2.98 is required for **chassis&Fabric support**.

Fixes

- Fix an issue that PLDM firmware update may fail. The issue may happen on controller, backplane and drive attached to controller.
-

Firmware Package - HPE MR416i-a Gen10 Plus Tri Mode Controller

Version: 52.26.3-5487 (**Recommended**)

Filename: HPE_MR416i-a_Gen10P_52.26.3-5487_A.fwpkg

Important Note!

- **This firmware version to be used on HPE MR416i-a Gen10 Plus Controller.**

Prerequisites

iLO5 version should be at least 2.98 is required for **chassis&Fabric support**.

Fixes

- Fix an issue that PLDM firmware update may fail. The issue may happen on controller, backplane and drive attached to controller.
-

Firmware Package - HPE MR416i-p Gen10 Plus Tri Mode Controller

Important Note!

- **This firmware version to be used on HPE MR416i-p Gen10 Plus Controller.**

Prerequisites

iLO5 version should be at least 2.98 is required for **chassis&Fabric support**.

Fixes

- Fix an issue that PLDM firmware update may fail. The issue may happen on controller, backplane and drive attached to controller.

Firmware Package - HPE SR932i-p Gen10 Plus /SR416i-a Gen10 Plus/SR932i-p Gen11/SR416ie-m Gen11 Controllers

Version: 03.01.30.106 (**Recommended**)

Filename: HPE_SR416_SR932_Gen10P_Gen11_03.01.30.106_A.fwpkg

Fixes

- Fixed an issue where the host experienced BSOD while clearing the controller configuration.
- Fixed controller lockups caused by incorrect address reads and partial RAM initialization for PCIe functions, leading to ECC errors.
- Fixed an issue where a possible controller lockup was observed after a factory reset.
- Fixed issues with external storage.
- Fixed issues with the SATA drive.
- Fixed issues with the SED drive.
- Fixed issues with the spare drive.
- Corrected MCTP-related issues.
- Fixed SPDM-related issues.
- Fixed issues related to volume creation and rebuilding.
- Fixed volume issues on the failed drive.
- Fixed surface scan issues on the RAID 50.
- Fixed issues encountered during heavy I/O operations.
- Fixed issues for incorrect Severity reported in Redfish events.
- Fixed issues for incorrect Status reported in Redfish resources.
- Fixed an issue with improper capacity information in Redfish drive Name.
- Fixed an issue where Redfish long running task status is not reported.
- Fixed an issue where DurableNameFormat for RAID volumes are reported as UUID in RDE READ operations, but should be NAA.
- Fixed an issue where failed to take ownership of, or to revert, a SED through Redfish.
- Fixed an issue when a drive hosting a RAID 0 Volume is removed and reinserted, a VolumeOK event is not generated.

Enhancements

- Added support for saving Managed SED master key and reset key in cipher text in controller NVRAM instead of clear text.
- Changed temperature polling period from 1 minute to 5 minutes for HBA mode drives that are in low power state.
- Added support for clearing UREs in unmapped LBA range of fault tolerant logical drives.
- Improved RAID 1/10 write sequential performance.
- Added support for SED encryption configuration through Redfish interface.
- Added support of Redfish Chassis implementation for UBM Backplanes.
- Added Redfish ACTION:
 - Storage.SetEncryptionKey
- Added support for Redfish property PATCH:
 - Storage.EncryptionMode
 - Storage.HotspareActivationPolicy
 - Drive.HostspareReplacementMode
 - Drive.HotspareType
 - Volume.Encrypted
- Added support for Redfish Status.Conditions property to resources:
 - Drive
 - Port
 - StorageController
 - StorageController.CacheSummary
 - Volume
- Added support for Redfish properties:
 - Drive.DriveFormFactor
 - Drive.FirmwareVersion
 - Drive.Manufacture (SAS only)
 - Drive.SlotCapableProtocols

- StorageController.AssetTag
- StorageController.Links.PCIeFunction
- Volume.BlockSizeBytes
- Volume.LogicalUnitNumber
- Added support for PLDM Type5 UBM PIC firmware flashing behind expander.

Online Firmware Flash for ESXi - HPE Gen10 Plus Boot Controller NS204i-p, NS204i-d, NS204i-t, NS204i-r

Version: 1.0.14.1063 **(Recommended)**

Filename: CP056151.compsig; CP056151.zip

Important Note!

- VMware **7.0u1 is** supported by HPE NS204i-p, NS204i-d, NS204i-t and NS204i-r Gen10+ Boot Controller
- **VMware 7.0 is NOT supported by HPE NS204i-p, NS204i-d, NS204i-t and NS204i-r Gen10+ Boot Controller**
- **This version is the minimum required version for Gen10 Plus device to upgrade to latest FW**
- **You can get Firmware Package version 1.2.14.1004 or latest FW version from <https://www.hpe.com/global/swpublishing/MTX-318c8e8298704d8bb4f991eb4d> and update it via iLO without any OS dependency.**

Fixes

Fix known issue on v1055 regarding RDE dictionary broken which will cause unexpected FW upgrading error.

Online ROM Flash Component for VMware ESXi - HPE 12Gb/s SAS Expander Firmware for HPE Smart Array Controllers and HPE HBA Controllers

Version: 5.15 (B) **(Recommended)**

Filename: CP057012.compsig; CP057012.zip

Important Note!

- **Do NOT downgrade FW to previous version if your current expander is 5.10; please upgrade to 5.15 immediately.**

Enhancements

- Support HPE ProLiant DL180 Gen10 Server

Online ROM Flash Component for VMware ESXi - HPE Smart Array P408i-p, P408e-p, P408i-a, E208i-p, E208e-p, E208i-a, P816i-a SR Gen10

Version: 5.61 (D) **(Recommended)**

Filename: CP057475.compsig; CP057475.zip

Enhancements

Support Gen10, Gen10 Plus and Gen11 servers

Online ROM Flash Component for VMware ESXi - HPE Smart Array P408i-p, P408e-p, P408i-a, E208i-p, E208e-p, E208i-a, P816i-a SR Gen10

Version: 7.11 **(Recommended)**

Filename: CP059505.compsig; CP059505.zip

Fixes

- Fixed an issue where the host experienced BSOD while clearing the controller configuration.
- Fixed controller lockups caused by incorrect address reads and partial RAM initialization for PCIe functions, leading to ECC errors.
- Fixed issues with external storage.
- Fixed issues with the SATA drive.
- Fixed issues with the SED drive.
- Fixed issues with the spare drive.
- Corrected MCTP-related issues.
- Fixed surface scan issues on the RAID 50.
- Fixed issues encountered during heavy I/O operations.
- Fixed volume issues on the failed drive.
- Fixed issues for incorrect Severity reported in Redfish events.
- Fixed issues for incorrect Status reported in Redfish resources.
- Fixed an issue with improper capacity information in Redfish drive Name.

Fixed an issue where Redfish long running task status is not reported.

- Fixed an issue where DurableNameFormat for RAID volumes are reported as UUID in RDE READ operations, but should be NAA.
- Fixed an issue where failed to take ownership of, or to revert, a SED through Redfish.
- Fixed an issue when a drive hosting a RAID 0 Volume is removed and reinserted, a VolumeOK event is not generated.

Enhancements

- Added support for saving Managed SED master key and reset key in cipher text in controller NVRAM instead of clear text.
- Changed temperature polling period from 1 minute to 5 minutes for HBA mode drives that are in low power state.
- Added support for clearing UREs in unmapped LBA range of fault tolerant logical drives.
- Improved random write and mixed read-write performance.
- Added support for SED encryption configuration through Redfish interface.
- Added support of Redfish Chassis implementation for UBM Backplanes.
- Added Redfish ACTION:
 - Storage.SetEncryptionKey
- Added support for Redfish property PATCH:
 - Storage.EncryptionMode
 - Storage.HotspareActivationPolicy
 - Drive.HostspareReplacementMode
 - Drive.HotspareType
 - Volume.Encrypted
- Added support for Redfish Status.Conditions property to resources:
 - Drive
 - Port
 - StorageController
 - StorageController.CacheSummary
 - Volume
- Added support for Redfish properties:
 - Drive.DriveFormFactor
 - Drive.FirmwareVersion
 - Drive.Manufacture (SAS only)
 - Drive.SlotCapableProtocols
 - StorageController.AssetTag
 - StorageController.Links.PCIeFunction
 - Volume.BlockSizeBytes
 - Volume.LogicalUnitNumber
- Added support for PLDM Type5 UBM PIC firmware flashing behind expander.

Firmware - Storage Fibre Channel

[Top](#)

HPE Firmware Flash for Emulex Fibre Channel Host Bus Adapters for VMware vSphere 8.0

Version: 2024.09.01 **(Recommended)**

Filename: CP059672.compsig; CP059672.zip

Important Note!

Release notes:

[Broadcom Release notes](#)

This Firmware package contains following firmware versions:

| Adapter | Speed | Universal Boot Image | Firmware | UEFI | Boot Bios |
|---|-------|----------------------|-------------|------------|------------|
| HPE SN1200E 16Gb Dual Port Fibre Channel Host Bus Adapter | 16Gb | 14.4.329.10 | 14.4.329.10 | 14.4.329.9 | 14.4.290.0 |
| HPE SN1200E 16Gb Single Port Fibre Channel Host Bus Adapter | 16Gb | 14.4.329.10 | 14.4.329.10 | 14.4.329.9 | 14.4.290.0 |
| HPE SN1600E 32Gb Dual Port Fibre Channel Host Bus Adapter | 32Gb | 14.4.329.10 | 14.4.329.10 | 14.4.329.9 | 14.4.290.0 |
| HPE SN1600E 32Gb Single Port Fibre Channel Host Bus Adapter | 32Gb | 14.4.329.10 | 14.4.329.10 | 14.4.329.9 | 14.4.290.0 |
| HPE SN1610E 32Gb Single Port Fibre Channel Host Bus Adapter | 32Gb | 14.4.329.10 | 14.4.329.10 | 14.4.329.9 | 14.4.290.0 |
| HPE SN1610E 32Gb Dual Port Fibre Channel Host Bus Adapter | 32Gb | 14.4.329.10 | 14.4.329.10 | 14.4.329.9 | 14.4.290.0 |
| HPE SN1700E 64Gb Single Port Fibre Channel Host Bus Adapter | 64Gb | 14.4.329.10 | 14.4.329.10 | 14.4.329.9 | 14.4.290.0 |
| HPE SN1700E 64Gb Dual Port Fibre Channel Host Bus Adapter | 64Gb | 14.4.329.10 | 14.4.329.10 | 14.4.329.9 | 14.4.290.0 |

Prerequisites

Please consult SPOCK for a list of supported configurations available at the following link:

<http://www.hpe.com/storage/spock/>

Enhancements

This Firmware package contains following firmware versions:

| Adapter | Speed | Universal Boot Image | Firmware | UEFI | Boot Bios |
|---|-------|----------------------|-------------|------------|------------|
| HPE SN1200E 16Gb Dual Port Fibre Channel Host Bus Adapter | 16Gb | 14.4.329.10 | 14.4.329.10 | 14.4.329.9 | 14.4.290.0 |
| HPE SN1200E 16Gb Single Port Fibre Channel Host Bus Adapter | 16Gb | 14.4.329.10 | 14.4.329.10 | 14.4.329.9 | 14.4.290.0 |
| HPE SN1600E 32Gb Dual Port Fibre Channel Host Bus Adapter | 32Gb | 14.4.329.10 | 14.4.329.10 | 14.4.329.9 | 14.4.290.0 |
| HPE SN1600E 32Gb Single Port Fibre Channel Host Bus Adapter | 32Gb | 14.4.329.10 | 14.4.329.10 | 14.4.329.9 | 14.4.290.0 |
| HPE SN1610E 32Gb Single Port Fibre Channel Host Bus Adapter | 32Gb | 14.4.329.10 | 14.4.329.10 | 14.4.329.9 | 14.4.290.0 |
| HPE SN1610E 32Gb Dual Port Fibre Channel Host Bus Adapter | 32Gb | 14.4.329.10 | 14.4.329.10 | 14.4.329.9 | 14.4.290.0 |
| HPE SN1700E 64Gb Single Port Fibre Channel Host Bus Adapter | 64Gb | 14.4.329.10 | 14.4.329.10 | 14.4.329.9 | 14.4.290.0 |
| HPE SN1700E 64Gb Dual Port Fibre Channel Host Bus Adapter | 64Gb | 14.4.329.10 | 14.4.329.10 | 14.4.329.9 | 14.4.290.0 |

Supported Devices and Features

This component is supported on following Emulex Fibre Channel Host Bus adapters:

16Gb FC Adapter:

- HPE SN1200E 16Gb Dual Port Fibre Channel Host Bus Adapter
- HPE SN1200E 16Gb Single Port Fibre Channel Host Bus Adapter

32Gb FC Adapter:

- HPE SN1600E 32Gb Dual Port Fibre Channel Host Bus Adapter
- HPE SN1600E 32Gb Single Port Fibre Channel Host Bus Adapter
- HPE SN1610E 32Gb Dual port Fibre Channel Host Bus Adapter
- HPE SN1610E 32Gb Single port Fibre Channel Host Bus Adapter

64Gb FC Adapter:

- HPE SN1700E 64Gb Dual Port Fibre Channel Host Bus Adapter
- HPE SN1700E 64Gb Single Port Fibre Channel Host Bus Adapter

HPE Firmware Flash for QLogic Fibre Channel Host Bus Adapters for VMware vSphere 8.0

Version: 2024.09.01 (**Recommended**)

Filename: CP059846.compsig; CP059846.zip

Important Note!

Release Notes:

[HPE QLogic Adapters Release Notes](#)

This Firmware package contains following firmware versions:

| Adapter | Speed | MBI | Firmware | UEFI | Boot Bios |
|--|-------|----------|----------|------|-----------|
| HPE SN1100Q 16GB Dual Port PCIe Fibre Channel Host Bus Adapter | 16Gb | 02.04.01 | 9.15.00 | 7.25 | 3.68 |
| HPE SN1100Q 16GB Single Port PCIe Fibre Channel Host Bus Adapter | 16Gb | 02.04.01 | 9.15.00 | 7.25 | 3.68 |
| HPE SN1600Q 32Gb Single Port Fibre Channel Host Bus Adapter | 32Gb | 02.04.01 | 9.15.00 | 7.25 | 3.68 |
| HPE SN1600Q 32Gb Dual Port Fibre Channel Host Bus Adapter | 32Gb | 02.04.01 | 9.15.00 | 7.25 | 3.68 |
| HPE SN1610Q 32Gb Dual Port Fibre Channel Host Bus Adapter | 32Gb | 02.10.00 | 09.15.00 | 7.36 | 0.0 |
| HPE SN1610Q 32Gb Single Port Fibre Channel Host Bus Adapter | 32Gb | 02.10.00 | 09.15.00 | 7.36 | 0.0 |
| HPE SN1700Q 64Gb Dual Port Fibre Channel Host Bus Adapter | 64Gb | 02.10.00 | 09.15.00 | 7.36 | 0.0 |
| HPE SN1700Q 64Gb Single Port Fibre Channel Host Bus Adapter | 64Gb | 02.10.00 | 09.15.00 | 7.36 | 0.0 |

Prerequisites

Please consult SPOCK for a list of supported configurations available at the following link:

<http://www.hpe.com/storage/spock/>

Enhancements

This Firmware package contains following firmware versions:

| Adapter | Speed | MBI | Firmware | UEFI | Boot Bios |
|--|-------|----------|----------|------|-----------|
| HPE SN1100Q 16GB Dual Port PCIe Fibre Channel Host Bus Adapter | 16Gb | 02.04.01 | 9.15.00 | 7.25 | 3.68 |
| HPE SN1100Q 16GB Single Port PCIe Fibre Channel Host Bus Adapter | 16Gb | 02.04.01 | 9.15.00 | 7.25 | 3.68 |
| HPE SN1600Q 32Gb Single Port Fibre Channel Host Bus Adapter | 32Gb | 02.04.01 | 9.15.00 | 7.25 | 3.68 |
| HPE SN1600Q 32Gb Dual Port Fibre Channel Host Bus Adapter | 32Gb | 02.04.01 | 9.15.00 | 7.25 | 3.68 |
| HPE SN1610Q 32Gb Dual Port Fibre Channel Host Bus Adapter | 32Gb | 02.10.00 | 09.15.00 | 7.36 | 0.0 |
| HPE SN1610Q 32Gb Single Port Fibre Channel Host Bus Adapter | 32Gb | 02.10.00 | 09.15.00 | 7.36 | 0.0 |
| HPE SN1700Q 64Gb Dual Port Fibre Channel Host Bus Adapter | 64Gb | 02.10.00 | 09.15.00 | 7.36 | 0.0 |
| HPE SN1700Q 64Gb Single Port Fibre Channel Host Bus Adapter | 64Gb | 02.10.00 | 09.15.00 | 7.36 | 0.0 |

Supported Devices and Features

This component is supported on following Qlogic Fibre Channel Host Bus adapters:

16Gb Fibre Channel Host Bus Adapter:

- HPE SN1100Q 16GB Dual Port PCIe Fibre Channel Host Bus Adapter
- HPE SN1100Q 16GB Single Port PCIe Fibre Channel Host Bus Adapter

32Gb Fibre Channel Host Bus Adapter:

- HPE SN1600Q 32Gb Single Port Fibre Channel Host Bus Adapter
- HPE SN1600Q 32Gb Dual Port Fibre Channel Host Bus Adapter
- HPE SN1610Q 32Gb Dual Port Fibre Channel Host Bus Adapter
- HPE SN1610Q 32Gb Single Port Fibre Channel Host Bus Adapter

64Gb Fibre Channel Host Bus Adapter:

- HPE SN1700Q 64Gb Dual Port Fibre Channel Host Bus Adapter
- HPE SN1700Q 64Gb Single Port Fibre Channel Host Bus Adapter

Software - Management

HPE Agentless Management Bundle Smart Component on ESXi for Gen10 and Gen10 Plus Servers

Version: 2024.03.01 (**Recommended**)

Filename: cp059815.compsig; cp059815.zip

[Top](#)

Fixes

Agentless Management Service

- Fixed OID name hrSystemUptime is reported incorrectly

Smart Storage Administrator (SSA) CLI Smart Component for ESXi 8.0 for Gen10/Gen10 Plus/Gen11 Controllers

Version: 2024.10.01 (**Recommended**)

Filename: cp059215.compsig; cp059215.zip

Important Note!

Actual ESXi Version is 6.40.6.0

Fixes

- Fixed an issue on VMware ESXi 8.0 U2 where not all controllers were shown via esxcli.
- Fixed an issue on VMware ESXi 8.0 U2 where the create and delete config, as well as other modify operations, were not working.

- Fixed an issue where failed drive details were displayed multiple times in the 'show config' output.
- Fixed incorrect error messages displayed in SSACLI when the modify command threw an error if the 'drive' and 'drivetype' parameters coexisted.
- Fixed an issue where the array creation command failed when executed with the drives=all and drivetype=sata_hdd parameters.
- Fixed an issue where the drives behind the enclosures were missing in the SSACLI output.
- Fixed an issue where users encountered a failure when launching the SSASCRIPITING tool to restore a RAID configuration with an unsupported parameter for PrebootHealthReporting.

Enhancements

- To improve the output format of the NVMe drive health log for the show command.
-

Software - Storage Controller

[Top](#)

HPE MegaRAID Storage Administrator StorCLI for VMware8.0 (For Gen10P and Gen11 Controllers)

Version: 2024.06.01 **(Recommended)**

Filename: cp060804.compsig; cp060804.zip

Fixes

Fix an issue that VMware 8.0 command throws storcli pluggin error.

Enhancements

- Support new HPE ProLiant DL145 Gen11 server.
-

Software - Storage Fibre Channel

[Top](#)

HPE QLogic Fibre Channel driver component for VMware vSphere 8.0

Version: 2024.09.01 **(Recommended)**

Filename: cp061880.compsig; cp061880.zip

Important Note!

Release Notes:

[HPE QLogic Adapters Release Notes](#)

This component is intended to be used by HPE applications. It is a zip that contains the same driver deliverable available from the vmware.com and the HPE vibsdepot.hpe.com webpages, plus an HPE specific CPXXXX.xml file.

This driver is only supported on VMware ESXi 8.0u3

Prerequisites

Please consult SPOCK for a list of supported configurations available at the following link:

<http://www.hpe.com/storage/spock/>

Enhancements

Driver version 5.4.83.1

This driver is only supported on VMware ESXi 8.0u3

Supported Devices and Features

This component is supported on following Qlogic Fibre Channel Host Bus adapters:

16Gb Fibre Channel Host Bus Adapter:

- HPE SN1100Q 16GB Dual Port PCIe Fibre Channel Host Bus Adapter
- HPE SN1100Q 16GB Single Port PCIe Fibre Channel Host Bus Adapter

32Gb Fibre Channel Host Bus Adapter:

- HPE SN1600Q 32Gb Single Port Fibre Channel Host Bus Adapter
- HPE SN1600Q 32Gb Dual Port Fibre Channel Host Bus Adapter
- HPE SN1610Q 32Gb Dual Port Fibre Channel Host Bus Adapter
- HPE SN1610Q 32Gb Single Port Fibre Channel Host Bus Adapter

64Gb Fibre Channel Host Bus Adapter:

- HPE SN1700Q 64Gb Dual Port Fibre Channel Host Bus Adapter
- HPE SN1700Q 64Gb Single Port Fibre Channel Host Bus Adapter

HPE QLogic Fibre Channel driver component for VMware vSphere 8.0
Version: 2024.09.01 **(Recommended)**
Filename: cp062113.compsig; cp062113.zip

Important Note!

Release Notes:

[HPE QLogic Adapters Release Notes](#)

This component is intended to be used by HPE applications. It is a zip that contains the same driver deliverable available from the vmware.com and the HPE vibsdepot.hpe.com webpages, plus an HPE specific CPXXXX.xml file.

Prerequisites

Please consult SPOCK for a list of supported configurations available at the following link:

<http://www.hpe.com/storage/spock/>

Enhancements

Driver version 5.4.82.1

Supported Devices and Features

This component is supported on following Qlogic Fibre Channel Host Bus adapters:

16Gb Fibre Channel Host Bus Adapter:

- HPE SN1100Q 16GB Dual Port PCIe Fibre Channel Host Bus Adapter
- HPE SN1100Q 16GB Single Port PCIe Fibre Channel Host Bus Adapter

32Gb Fibre Channel Host Bus Adapter:

- HPE SN1600Q 32Gb Single Port Fibre Channel Host Bus Adapter
- HPE SN1600Q 32Gb Dual Port Fibre Channel Host Bus Adapter
- HPE SN1610Q 32Gb Dual Port Fibre Channel Host Bus Adapter
- HPE SN1610Q 32Gb Single Port Fibre Channel Host Bus Adapter

64Gb Fibre Channel Host Bus Adapter:

- HPE SN1700Q 64Gb Dual Port Fibre Channel Host Bus Adapter
- HPE SN1700Q 64Gb Single Port Fibre Channel Host Bus Adapter

Software - System Management

HPE Agentless Management Bundle for ESXi for HPE Gen10 and Gen10 Plus Servers
Version: 701.11.10.0 **(Recommended)**
Filename: amsdComponent_701.11.10.0.4-1_23433471.zip

[Top](#)

Fixes

Agentless Management Service

- Fixed OID name hrSystemUptime is reported incorrectly

HPE Fiber Channel and Storage Enablement Component for ESXi 8.0
Version: 3.9.0 **(Recommended)**
Filename: fc-enablement-component_800.3.9.0.30-1_20300413.zip

Enhancements

Supports VMware ESXi 8.0

Get connected

hpe.com/info/getconnected

Current HPE driver, support, and security alerts delivered directly to your desktop

© Copyright 2022 Hewlett Packard Enterprise Development Company, L.P.

The information contained herein is subject to change without notice. The only warranties for HPE products and services are set forth in the express warranty statements accompanying such products and services. Nothing herein should be construed as constituting an additional warranty. HPE shall not be liable for technical or editorial errors or omissions contained herein.

Trademark acknowledgments, if needed.

Updated September 26 2024

